



AUDI A 4

A4 2.0 TDI Ambition

VIN NO WAUZZZ8E45A460567
Registration Number AJ566JP



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCA Auto Encheres	Report Number	P20250901111450
Inspection Date / Place	2025-09-01 / BCA GUERLESQUIN	Cosmetic Grade	5


Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Exempt Rate
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Grey	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	4
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	153

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage	Normal Use	Imported	
Manufacturer Warranty			





Equipment


Central locking	Radio	Cruise control	Power assisted steering
Electrically adjustable seats	Stability control	Front fog lamps	Satellite navigation

Equipment Details


Seat Heating	Front	Air Conditioning	No
Sunroof Type	Tilt/Slide Steel		

Cosmetic Damage

31 Dommages




0 Dommages




Component		Damage	Comments
1	Fender / Front Left	Paint / Scratch / Scuff	
2	Fender / Front Left	Bodywork / Breakage	
3	Fender / Front Left	Bodywork / Dent / Dent	
4	Fender / Front Left	Paint / Scratch / Line	
5	Door / Back Left	Paint / Scratch / Line	
6	Door / Back Left	Bodywork / Dent / Dent	
7	Door / Back Left	Paint / Poor Previous Repair	
8	Door / Back Left	Paint / Scratch / Scuff	
9	Door / Back Left	Bodywork / Dent / Dent	
10	Door / Back Left	Paint / Scratch / Line	
11	Bumper / Back	Paint / Scratch / Line	
12	Bumper / Back	Paint / Scratch / Line	

13	Bumper / Back	Paint / Chipping
14	Bumper / Back	Paint / Poor Previous Repair
15	Side Panel / Back Right	Paint / Scratch / Scuff
16	Side Panel / Back Right	Paint / Scratch / Line
17	Side Panel / Back Right	Paint / Scratch / Scuff
18	Side Panel / Back Right	Paint / Scratch / Scuff
19	Side Panel / Back Right	Paint / Scratch / Line
20	Fender / Front Right	Paint / Stone Chip
21	Fender / Front Right	Paint / Scratch / Scuff
22	Fender / Front Right	Paint / Scratch / Line
23	Fender / Front Right	Bodywork / Dent / Dent
24	Fender / Front Right	Bodywork / Breakage / Crack
25	Fender / Front Right	Paint / Scratch / Scuff
26	Hood	Paint / Scratch / Scuff
27	Hood	Paint / Scratch / Scuff
28	Hood	Bodywork / Dent / Dent
29	Hood	Paint / Scratch / Line
30	Hood	Paint / Stone Chip
31	Windshield Joint / Front	Paint / Chemical Damage



1. Fender / Front Left
Paint / Scratch / Scuff -



2. Fender / Front Left
Bodywork / Breakage -



3. Fender / Front Left
Bodywork / Dent / Dent -



4. Fender / Front Left
Paint / Scratch / Line -



5. Door / Back Left
Paint / Scratch / Line -



6. Door / Back Left
Bodywork / Dent / Dent -



7. Door / Back Left
Paint / Poor Previous Repair -



8. Door / Back Left
Paint / Scratch / Scuff -



9. Door / Back Left
Bodywork / Dent / Dent -



10. Door / Back Left
Paint / Scratch / Line -



11. Bumper / Back
Paint / Scratch / Line -



12. Bumper / Back
Paint / Scratch / Line -



13. Bumper / Back
Paint / Chipping -



14. Bumper / Back
Paint / Poor Previous Repair -



15. Side Panel / Back Right
Paint / Scratch / Scuff -



16. Side Panel / Back Right
Paint / Scratch / Line -



17. Side Panel / Back Right
Paint / Scratch / Scuff -



18. Side Panel / Back Right
Paint / Scratch / Scuff -



19. Side Panel / Back Right
Paint / Scratch / Line -



20. Fender / Front Right
Paint / Stone Chip -



21. Fender / Front Right
Paint / Scratch / Scuff -



22. Fender / Front Right
Paint / Scratch / Line -



23. Fender / Front Right
Bodywork / Dent / Dent -



24. Fender / Front Right
Bodywork / Breakage / Crack -



25. Fender / Front Right
Paint / Scratch / Scuff -



26. Hood
Paint / Scratch / Scuff -



27. Hood
Paint / Scratch / Scuff -



28. Hood
Bodywork / Dent / Dent -



29. Hood
Paint / Scratch / Line -



30. Hood
Paint / Stone Chip -



31. Windshield Joint / Front
Paint / Chemical Damage -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.