



AUDI A4

A4 Avant 2.0 TDI DPF

VIN NO WAUZZZ8K1BA083794
Registration Number K1BA083794



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-12-01	2	2	235044 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2011-03-24	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20251010093022
Inspection Date / Place	2025-10-10 / BCA Neuss	Cosmetic Grade	5

Vehicle Summary



Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Grey	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	135

Vehicle History & Documents

Service Book Available	Incomplete	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Airbag Status	Anti-lock braking	Bluetooth telephone interface	Diesel particulate filter
Headlamp wash/wipe	Remote adjusting wing mirrors	Roof rails	Xenon headlamps
Electrically folding wing mirrors	Radio	Alloys wheels	Auxiliary Socket
Cruise control	Front fog lamps	Heated wing mirrors	Remote central locking
Satellite navigation	CD Player	Leather steering wheel	Rear parking sensors

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	18
Extra Wheel / Tyre Set	Winter Tyres - Steel	Seat Heating	Front

Wheels & Tyres


Extra Wheel - 1 Tyre Depth	6	Extra Wheel - 2 Tyre Depth	6
Extra Wheel - 3 Tyre Depth	7	Extra Wheel - 4 Tyre Depth	7
Right Front Tyre Depth	3	Left Front Tyre Depth	3
Right Rear Tyre Depth	3	Left Rear Tyre Depth	3

Cosmetic Damage

27 Schäden




28 Schäden



Component		Damage	Comments
1	Fender / Back Left	Paint / Poor Previous Repair	
2	Steering Wheel / Front	Interior / Scratched	
3	Bumper / Back	Paint / Scratch / Scuff	
4	Corner Bumper / Front Right	Paint / Scratch / Scuff	
5	Pillar / Back Right	Paint / Scratch / Scuff	
6	Bumper / Front	Paint / Scratch / Scuff	
7	Pillar / Back Left	Paint / Scratch / Scuff	
8	Corner Bumper / Front Left	Paint / Scratch / Scuff	
9	Door / Front Right	Paint / Scratch / Scuff	
10	Seat / Front Left	Interior / Scratched	
11	Fender / Back Left	Paint / Poor Previous Repair	
12	Corner Bumper / Back Left	Paint / Scratch / Scuff	

13	Fender / Back Right	Paint / Scratch / Scuff
14	Door / Back Left	Paint / Scratch / Scuff
15	Corner Bumper / Back Right	Paint / Scratch / Scuff
16	Hood	Bodywork / Dent / Dent
17	B Pillar / Center Left	Paint / Scratch / Scuff
18	Fender / Back Left	Paint / Scratch / Scuff
19	Fender / Back Right	Paint / Scratch / Scuff
20	Door / Back Right	Bodywork / Dent / Dent
21	Fender / Back Right	Bodywork / Dent / Dent
22	Fender / Back Left	Paint / Scratch / Scuff
23	Fender / Back Left	Paint / Scratch / Scuff
24	Door / Front Left	Paint / Poor Previous Repair
25	Door / Back Left	Paint / Poor Previous Repair
26	Fender / Back Left	Paint / Poor Previous Repair
27	Fender / Front Right	Paint / Poor Previous Repair
28	Rim / Back Right	Out of Bodywork / Scratch
29	Rim / Front Right	Out of Bodywork / Scratch



1. Fender / Back Left
Paint / Poor Previous Repair -




2. Steering Wheel / Front
Interior / Scratched -



3. Bumper / Back
Paint / Scratch / Scuff -



4. Corner Bumper / Front Right
Paint / Scratch / Scuff -



5. Pillar / Back Right
Paint / Scratch / Scuff -




6. Bumper / Front
Paint / Scratch / Scuff -



7. Pillar / Back Left
Paint / Scratch / Scuff -



8. Corner Bumper / Front Left
Paint / Scratch / Scuff -



9. Door / Front Right
Paint / Scratch / Scuff -



10. Seat / Front Left
Interior / Scratched -



11. Fender / Back Left
Paint / Poor Previous Repair -



12. Corner Bumper / Back Left
Paint / Scratch / Scuff -




13. Fender / Back Right
Paint / Scratch / Scuff -




14. Door / Back Left
Paint / Scratch / Scuff -



15. Corner Bumper / Back Right
Paint / Scratch / Scuff -



16. Hood
Bodywork / Dent / Dent -




17. B Pillar / Center Left
Paint / Scratch / Scuff -



18. Fender / Back Left
Paint / Scratch / Scuff -



19. Fender / Back Right
Paint / Scratch / Scuff -



20. Door / Back Right
Bodywork / Dent / Dent -



21. Fender / Back Right
Bodywork / Dent / Dent -



22. Fender / Back Left
Paint / Scratch / Scuff -



23. Fender / Back Left
Paint / Scratch / Scuff -



24. Door / Front Left
Paint / Poor Previous Repair -



25. Door / Back Left
Paint / Poor Previous Repair -



26. Fender / Back Left
Paint / Poor Previous Repair -



27. Fender / Front Right
Paint / Poor Previous Repair -



28. Rim / Back Right
Out of Bodywork / Scratch -



29. Rim / Front Right
Out of Bodywork / Scratch -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Display Defect	✓
Tire Pressure Monitoring System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Main & Spare Keys Functioning	!	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

Levels

Brakes Fluid	NA	Coolant Fluid	✓
--------------	----	---------------	---

Test Drive Inspection

Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly	✓		
Steering Wheel			
Steering Noise / Anomaly	✓		
Clutch			
Clutch Functioning	✓		
General			
Test Driven Status	✓		

- ✓ *No troubles detected, good condition or correct tests, according to vehicle age and mileage*
- ! *Damages or malfunction detected that requires repairs by the buyer*
- NA *Not applicable*
- ☐ *Not tested*

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)