



AUDI A4 Allroad Quattro

A4 allroad quattro 2.0 TDI DPF

VIN NO WAUZZZ8K3EA109199
Registration Number K3EA109199



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2027-02-01	3	2	125088 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2025-02-04	120085	2014-02-14	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250922092542
Inspection Date / Place	2025-09-22 / BCA Oberndorf	Cosmetic Grade	1

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Blue	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth/Leather
Charging Cables		NEDC CO2 Rating (q/km)	153
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Airbag Status	Anti-lock braking	Cruise control	Fatiguewarningsystem
Front parking sensors	Remote adjusting wing mirrors	Roof rails	Split folding rear seats
Xenon headlamps	Central locking	Radio	Rear parking sensors
Alloys wheels	Bluetooth telephone interface	Diesel particulate filter	Front fog lamps
Heated wing mirrors	Remote central locking	Satellite navigation	Stability control
CD Player	Leather steering wheel	Rain sensitive windscreen wipers	

Equipment Details


Air Conditioning	Three Zone Climate Control	Alloy Wheel Size	18
Extra Wheel / Tyre Set	Winter Tyres - Alloy	Seat Heating	Front

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5
Extra Wheel - 1 Tyre Depth	7	Extra Wheel - 2 Tyre Depth	7
Extra Wheel - 3 Tyre Depth	7	Extra Wheel - 4 Tyre Depth	7

Cosmetic Damage

4 Schäden



2 Schäden



Component		Damage	Comments
1	Blade/spoiler / Front	Paint / Scratch / Scuff	
2	Hood	Paint / Scratch / Line	
3	Seat / Front Left	Interior / Scratched	
4	Mirror / Front Right	Paint / Scratch / Scuff	
5	Wing Stick / Front Right	Paint / Scratch / Line	
6	Gear Knob	Interior / Scratched	



1. Blade/spoiler / Front
Paint / Scratch / Scuff -



2. Hood
Paint / Scratch / Line -



3. Seat / Front Left
Interior / Scratched -



4. Mirror / Front Right
Paint / Scratch / Scuff -



5. Wing Stick / Front Right
Paint / Scratch / Line -



6. Gear Knob
Interior / Scratched -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
All - wheel Drive	✓	No Dashboard Lights	✓

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Audio Equipment	✓
AC / Heating System	✓	Other Equipments	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Clutch			
Clutch Functioning		✓	
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		Not Performed	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)