



AUDI A 3

A3 1.6

VIN NO WAUZZZ8LZYA113028
Registration Number LZYA113028



MOT Date



Last Service



Number of Owners



Last Service Mileage



Number of Keys



First Registration Date



Odometer Reading



Country First Registered



Inspection Report Summary

Customer	BCA Online	Report Number	P20250919123026
Inspection Date / Place	2025-09-19 / Extern	Cosmetic Grade	5

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Unknown
Colour	Grey	Engine Size (cc)	1595
Engine Size	1.6	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Trip Computer	Anti-lock braking	Stability control	Central locking
Airbag Status	Remote adjusting wing mirrors	CD Player	Radio

Equipment Details


Air Conditioning	Climate Control	Seat Heating	No
------------------	-----------------	--------------	----

Wheels & Tyres


Right Front Tyre Depth	3	Left Front Tyre Depth	3
Right Rear Tyre Depth	6	Left Rear Tyre Depth	6

Cosmetic Damage

5 Schäden



2 Schäden



Component		Damage	Comments
1	Bumper / Front	Bodywork / Breakage	
2	Fender / Front Left	Bodywork / Dent / Dent	
3	Bumper / Back	Bodywork / Breakage	
4	Fender / Front Right	Paint / Scratch / Scuff	
5	Other	Paint / Poor Previous Repair	
6	Dashboard / Front	Interior / Holed	
7	Seat / Front Left	Interior / Burn	



1. Bumper / Front
Bodywork / Breakage -



2. Fender / Front Left
Bodywork / Dent / Dent -



3. Bumper / Back
Bodywork / Breakage -



4. Fender / Front Right
Paint / Scratch / Scuff -



5.
Paint / Poor Previous Repair -



6. Dashboard / Front
Interior / Holed -



7. Seat / Front Left
Interior / Burn -

Mechanical Condition

Control Lights

Display Defect	✓	ABS Warning Light	✓
ESP Fault/Traction Control Malfunction Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓		

Equipments Test

Central Locking	✓	Electric Windows	✓
Audio Equipment	✓	Other Equipments	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Clutch			
Clutch Functioning		✓	
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		NA	
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)