



AUDI A3 2003 Diesel
A3 1.9 tdi Attraction

VIN NO WAUZZZ8P04A164316
Registration Number CN408GZ



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2024-08-01	-	-	298441 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2004-04-26	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20250715113944
Inspection Date / Place	2025-07-15 / BCA Lodi	Cosmetic Grade	5


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Manual
Colour	Black	Engine Size (cc)	1896
Engine Size	1.9	No of Doors	3
Body Type	Sedan	Drive Train	Front
Seat Colour	Beige	No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	132

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment

Central locking	Alloys wheels	Parcel Shef	Remote central locking
Tyre Mobility Kit	Power assisted steering	Electrically folding wing mirrors	Remote adjusting wing mirrors
Trip Computer	Stability control		

Wheels & Tyres


Mounted Tires

Tyre / Wheel Type	Summer	
	YOKOHAMA	205/55//R16 - 94V / 4 mm
	YOKOHAMA	205/55//R16 - 94V / 4 mm
	WESTLAKE	205/55//R16 - 91V / 3 mm
	WESTLAKE	205/55//R16 - 91V / 3 mm

Cosmetic Damage

25 Danni

9 Danni



Component		Damage	Comments
1	Panel Filling / Front Left	Interior / Broken	
2	Seat / Front Left	Interior / Broken	
3	Dashboard / Front	Interior / Not Working	
4	Glovebox	Interior / Broken	
5	Aeration Grid / Front Center	Interior / Broken	
6	Roof Upholstery	Interior / Broken	
7	Cabin	Interior / Broken	
8	Windshield / Front	Glass Break / Impact	
9	Hood	Bodywork / Dent / Hail Area	
10	Hood	Bodywork / Dent	
11	Other	Bodywork / Breakage	
12	Rim / Front Left	Out of Bodywork / Scratch	
13	Mirror Shell / Front Left	Paint / Scratch / Line	

14	Side Window / Front Left	Missing Part
15	Door / Front Left	Bodywork / Dent
16	Fender / Back Left	Bodywork / Dent
17	Rim / Back Left	Out of Bodywork / Scratch
18	Back Light / Left	Glass Break
19	Bumper / Back	Bodywork / Dent
20	Tailgate	Bodywork / Dent
21	Fender / Back Right	Bodywork / Dent
22	Rim / Back Right	Out of Bodywork / Scratch
23	Door / Front Right	Bodywork / Dent
24	Mirror Shell / Front Right	Paint / Scratch / Line
25	Fender / Front Right	Paint / Scratch / Line
26	Rim / Front Right	Out of Bodywork / Scratch
27	Pillar / Front Right	Bodywork / Dent
28	Roof	Bodywork / Dent / Hail Area
29	Bumper / Front	Bodywork / Breakage
30	Bumper / Front	Bodywork / Breakage
31	Fender / Front Left	Bodywork / Dent
32	Floor Carpet	Interior / Burn
33	Cabin	Interior / Dirty
34	Pillar / Front Left	Bodywork / Dent



1. Panel Filling / Front Left
Interior / Broken -



2. Seat / Front Left
Interior / Broken -



3. Dashboard / Front
Interior / Not Working -



4. Glovebox
Interior / Broken -



5. Aeration Grid / Front Center
Interior / Broken -




6. Roof Upholstery
Interior / Broken -



7. Cabin
Interior / Broken -



8. Windshield / Front
Glass Break / Impact -



9. Hood
Bodywork / Dent / Hail Area -




10. Hood
Bodywork / Dent -



11.
Bodywork / Breakage -




12. Rim / Front Left
Out of Bodywork / Scratch -




13. Mirror Shell / Front Left
Paint / Scratch / Line -



14. Side Window / Front Left
Missing Part -



15. Door / Front Left
Bodywork / Dent -



16. Fender / Back Left
Bodywork / Dent -



17. Rim / Back Left
Out of Bodywork / Scratch -



18. Back Light / Left
Glass Break -



19. Bumper / Back
Bodywork / Dent -



20. Tailgate
Bodywork / Dent -



21. Fender / Back Right
Bodywork / Dent -



22. Rim / Back Right
Out of Bodywork / Scratch -



23. Door / Front Right
Bodywork / Dent -




24. Mirror Shell / Front Right
Paint / Scratch / Line -



25. Fender / Front Right
Paint / Scratch / Line -



26. Rim / Front Right
Out of Bodywork / Scratch -




27. Pillar / Front Right
Bodywork / Dent -



28. Roof
Bodywork / Dent / Hail Area -



29. Bumper / Front
Bodywork / Breakage -



30. Bumper / Front
Bodywork / Breakage -




31. Fender / Front Left
Bodywork / Dent -



32. Floor Carpet
Interior / Burn -



33. Cabin
Interior / Dirty -



34. Pillar / Front Left
Bodywork / Dent -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	!		
Equipments Test			
Other Equipments	!	AC / Heating System	!
Levels			
Brakes Fluid	✓	Coolant Fluid	✓

Test Drive Inspection

Other Checks			
Steering	✓	Brakes	✓
Suspension	!		
Gearbox			
Manual Gearbox	✓		
General			
Test Driven Status	✓	Test Drive Comment	A/C NON RAFFREDDA.
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	!
Engine Noise	!		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			