



AUDI A3/S3

A3 SportBack 2.0 FSI Ambiente

VIN NO WAUZZZ8P46A197600
Registration Number FT535RJ



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	-	1	145526 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2006-05-03	-

Inspection Report Summary

Customer	BCAauto Encheres	Report Number	P20250930062419
Inspection Date / Place	2025-09-30 / BCA BOUCHAIN	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Non-Runner	VAT Type	Exempt Rate
Fuel Type	Petrol	Gearbox Type	Manual
Colour	Black	Engine Size (cc)	1984
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Charging Cables		NEDC CO2 Rating (q/km)	166

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment


Central locking	Alloys wheels	Tow ball	Front fog lamps
Satellite navigation	Radio	Stability control	Cruise control
Power assisted steering			

Equipment Details

Seat Heating	No	Air Conditioning	Yes
Sunroof Type	Tilt/Slide Steel		

Cosmetic Damage

10 Dommages



0 Dommages



Component		Damage	Comments
1	Rim / Front Left	Out of Bodywork / Scratch	
2	Door / Front Left	Paint / Scratch / Scuff	
3	Fender / Back Left	Paint / Scratch / Scuff	
4	Bumper / Back	Paint / Scratch / Scuff	
5	Door / Back Right	Paint / Scratch / Scuff	
6	Door / Front Right	Paint / Scratch / Scuff	
7	Fender / Front Right	Paint / Scratch / Scuff	
8	Rim / Front Right	Out of Bodywork / Scratch	
9	Bumper / Front	Paint / Scratch / Scuff	
10	Bumper / Front	Paint / Scratch / Scuff	



1. Rim / Front Left
Out of Bodywork / Scratch -



2. Door / Front Left
Paint / Scratch / Scuff -



3. Fender / Back Left
Paint / Scratch / Scuff -



4. Bumper / Back
Paint / Scratch / Scuff -



5. Door / Back Right
Paint / Scratch / Scuff -



6. Door / Front Right
Paint / Scratch / Scuff -



7. Fender / Front Right
Paint / Scratch / Scuff -



8. Rim / Front Right
Out of Bodywork / Scratch -



9. Bumper / Front
Paint / Scratch / Scuff -



10. Bumper / Front
Paint / Scratch / Scuff -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.