



AUDI A3
A3 1.4 TFSI Sportback

VIN NO WAUZZZ8P99A065954
Registration Number P99A065954



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2026-05-01	2	2	157870 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2008-11-10	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250923142835
Inspection Date / Place	2025-09-23 / BCA Neuss	Cosmetic Grade	4

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Beige	Engine Size (cc)	1390
Engine Size	1.4	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Meridian schwarz	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	134
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Airbag Status	Anti-lock braking	Cruise control	Remote adjusting wing mirrors
Stability control	Leather steering wheel	Rear parking sensors	Alloys wheels
Bi Xenon Headlamps	Front fog lamps	Remote central locking	CD Player
Radio			


Equipment Details

Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	16
------------------	---------------------------	------------------	----


Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

22 Schäden



5 Schäden

6/14 - Report Number P20250923142835

13	Roof	Bodywork / Dent / Dent
14	Fender / Back Right	Paint / Scratch / Scuff
15	Fender / Back Right	Paint / Scratch / Scuff
16	Bumper / Back	Paint / Scratch / Scuff
17	Bumper / Back	Paint / Scratch / Scuff
18	Bumper / Back	Paint / Scratch / Scuff
19	Fender / Back Left	Paint / Scratch / Scuff
20	Mirror / Front Left	Paint / Scratch / Scuff
21	Door / Front Left	Paint / Scratch / Scuff
22	Door / Front Left	Bodywork / Dent / Dent
23	Door Joint / Front Left Middle	Bodywork / Breakage
24	Seat / Front Left	Interior / Worn - out
25	Steering Wheel / Front	Interior / Worn - out
26	Gear Knob	Interior / Broken
27	Seat / Front Left	Interior / Broken



1. Rim / Front Right
Out of Bodywork / Scratch -




2. Rim / Back Right
Out of Bodywork / Scratch -



3. Rim / Front Left
Out of Bodywork / Scratch -



4. Fender / Front Left
Paint / Scratch / Scuff -



5. Bumper / Front
Paint / Scratch / Scuff -



6. Bumper / Front
Paint / Scratch / Scuff -




7. Fender / Front Right
Paint / Corrosion -




8. Fender / Front Right
Paint / Scratch / Scuff -



9. Fender / Front Right
Paint / Scratch / Scuff -




10. Mirror / Front Right
Bodywork / Breakage -



11. Mirror / Front Right
Paint / Scratch / Scuff -



12. Center Console
Interior / Broken -



13. Roof
Bodywork / Dent / Dent -



14. Fender / Back Right
Paint / Scratch / Scuff -




15. Fender / Back Right
Paint / Scratch / Scuff -




16. Bumper / Back
Paint / Scratch / Scuff -




17. Bumper / Back
Paint / Scratch / Scuff -




18. Bumper / Back
Paint / Scratch / Scuff -




19. Fender / Back Left
Paint / Scratch / Scuff -



20. Mirror / Front Left
Paint / Scratch / Scuff -



21. Door / Front Left
Paint / Scratch / Scuff -



22. Door / Front Left
Bodywork / Dent / Dent -



23. Door Joint / Front Left Middle
Bodywork / Breakage -



24. Seat / Front Left
Interior / Worn - out -



25. Steering Wheel / Front
Interior / Worn - out -



26. Gear Knob
Interior / Broken -



27. Seat / Front Left
Interior / Broken -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	!
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Tire Pressure Monitoring System	✓		

Equipments Test

Main & Spare Keys Functioning	!	Electric Windows	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

Engine

Engine Status / EML	!	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	!
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✔	
Engine			
Engine Noise	✔	The Gears Scratch / Skip / Abnormal Operation	✔
Fume Quantity	✔	Power Loss	✔
Clutch			
Clutch Functioning		✔	
Brake			
Brake System Anomaly		✔	
General			
Test Driven Status		✔	
✔ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
= Not tested			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)