



Brand:	Audi	Mileage(km):	261921
Model:	Q5	Number of doors:	5
Model type:	3.0 TDI SQ5 quattro Pro Line Pano ACC B&O Trekhaak Camera	Vehicle length (cm):	
License plate:	KJ749P	Vehicle width (cm):	
Report code:	8970	Vehicle height (cm):	
Chassis number:	WAUZZZ8R1EA078970	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front+Rear
First int. reg.:	05/02/2014	Power(kw):	230
First NL reg.:	20/09/2016	Transmission	Automatic
Color:	Black <input checked="" type="checkbox"/> Metallic	Number of gears	8
Weight (kg)(kg):	1995	Displacement(cc):	2967
Empty weight(kg):	1895	Number of cylinders:	6
Wheelbase (cm)(cm):	281	Fuel type:	Diesel
Top speed (km/h):	250	Fuel tank capacity:	
Cons. in the city (l/100 km):	7.6	EU category:	Euro 5
Cons. outside the city (l/100 km):	6.4	Energy label:	G
Average consumption (l/100 km):	6.8	NL Tax Rate %:	25
Acceleration (s):	5.1	CO2 (g/km):	179
Cargo space (l):	1995	Nb. of Axles:	2
Perm. max weight (kg):	2530	APK date:	08/05/2026

opties

<input checked="" type="checkbox"/> Alloy wheels	<input checked="" type="checkbox"/> Privacy glass	<input checked="" type="checkbox"/> Large screen navigation
<input checked="" type="checkbox"/> Leather upholstery	<input checked="" type="checkbox"/> Rain sensor	<input checked="" type="checkbox"/> Electrically operated rear windows
<input checked="" type="checkbox"/> Daytime running lights	<input checked="" type="checkbox"/> Rear wiper	<input checked="" type="checkbox"/> Electrically operated front windows
<input checked="" type="checkbox"/> Licht Sensor	<input checked="" type="checkbox"/> Rear view camera	<input checked="" type="checkbox"/> Electrically folding mirrors
<input checked="" type="checkbox"/> Towing hook	<input checked="" type="checkbox"/> Rear parking sensors	<input checked="" type="checkbox"/> Electrically adjustable mirrors
<input checked="" type="checkbox"/> Anti-lock braking system	<input checked="" type="checkbox"/> Front parking sensors	<input checked="" type="checkbox"/> Electrically adjustable driver's seat
<input checked="" type="checkbox"/> ABS	<input checked="" type="checkbox"/> Towbar with retractable ball	<input checked="" type="checkbox"/> Electrically adjustable passenger seat
<input checked="" type="checkbox"/> Airbag(s)	<input checked="" type="checkbox"/> Baggage separation net	<input checked="" type="checkbox"/> Electrically heated driver's seat
<input checked="" type="checkbox"/> Audio	<input checked="" type="checkbox"/> Luggage cover	<input checked="" type="checkbox"/> Electrically heated passenger seat
<input checked="" type="checkbox"/> Central locking system	<input checked="" type="checkbox"/> Trunk opens electrically	<input checked="" type="checkbox"/> Central armrest front
<input checked="" type="checkbox"/> Fog lamps	<input checked="" type="checkbox"/> USB connection	<input checked="" type="checkbox"/> Sport seats
<input checked="" type="checkbox"/> Power steering	<input checked="" type="checkbox"/> Radio/CD player	<input checked="" type="checkbox"/> Extendable passenger seat
<input checked="" type="checkbox"/> Front seats adjustable in height	<input checked="" type="checkbox"/> Bluetooth car kit	<input checked="" type="checkbox"/> Extendable driver's seat
<input checked="" type="checkbox"/> Multifunctional steering wheel	<input checked="" type="checkbox"/> Cruise control (adaptive)	<input checked="" type="checkbox"/> Adjustable lumbar support driver's seat
<input checked="" type="checkbox"/> Remote central locking	<input checked="" type="checkbox"/> Cruise control	<input checked="" type="checkbox"/> Adjustable lumbar support passenger seat
<input checked="" type="checkbox"/> Sports package (exterior)	<input checked="" type="checkbox"/> Sports package (interior)	<input checked="" type="checkbox"/> Audio control on the steering wheel
<input checked="" type="checkbox"/> Roof rail (silver)	<input checked="" type="checkbox"/> Black top interior	<input checked="" type="checkbox"/> Leather sports steering wheel
<input checked="" type="checkbox"/> Metallic finish	<input checked="" type="checkbox"/> Airconditioning	<input checked="" type="checkbox"/> Leather steering wheel
<input checked="" type="checkbox"/> Panoramic roof (electrical)	<input checked="" type="checkbox"/> Airconditioning in the back	<input checked="" type="checkbox"/> Switch flippers
<input checked="" type="checkbox"/> Xenon headlights	<input checked="" type="checkbox"/> Climate control	<input checked="" type="checkbox"/> Lane assistance
<input checked="" type="checkbox"/> Xenon headlights (adaptive)	<input checked="" type="checkbox"/> Climate control (digital)	
<input checked="" type="checkbox"/> Headlight washers	<input checked="" type="checkbox"/> Climate control (L/R separated)	

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	255/45 R20	Michelin	7
Tire left rear	Summer	Alloy	255/45 R20	Michelin	7
Tire right front	Summer	Alloy	255/45 R20	Michelin	7
Tire right rear	Summer	Alloy	255/45 R20	Michelin	7

Additional information

No. of keys:	2	<input type="checkbox"/> Luxury key	<input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black	Maintenance booklet:		<input checked="" type="checkbox"/> Odorless
Upholstery:	Leder			<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5	Stamp date:		<input checked="" type="checkbox"/> Display ok

No. of headrests:

5

Last turn mileage(km):

☒ Vehicle special usage (None)

Cleaning

☒ Clean inside (Interior is clean)

☐ Clean outside

Damages

 Not acceptable



Front left rim - Scratch



Rear left rim - Scratch



Rear right rim - Scratch



Front right rim - Scratch



Left headlight - Break



Windscreen - Pip




Front left screen - Scratch



Front left door - Rust formation



Rear bumper - Scratch



Rear right screen - Scratch



Right outside mirror - Scratch



beschadigd interieur

