



AUDI Q5
Q5 2.0 TDI quattro (clean diesel)

VIN NO WAUZZZ8R3HA089327
Registration Number R3HA089327



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	-	1	68405 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2025-03-07	66853	2017-07-04	-

Inspection Report Summary

Customer	BCA Online	Report Number	P20250926092630
Inspection Date / Place	2025-09-26 / Extern	Cosmetic Grade	2

Vehicle Summary



Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Grey	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth/Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	147
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Computer Print Out Available	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tow ball	Airbag Status	Anti-lock braking	Cruise control
Front parking sensors	Remote central locking	Satellite navigation	Sunroof
Electrically folding wing mirrors	Leather steering wheel	Rear parking sensors	Trip Computer
Alloys wheels	Bluetooth telephone interface	Diesel particulate filter	Remote adjusting wing mirrors
Roof rails	Stability control	CD Player	Electrictailgate

Radio

Equipment Details


Tow Ball Type	Pivoted	Air Conditioning	Dual Zone Climate Control
Alloy Wheel Size	19	Seat Heating	Front
Sunroof Type	Opening Panoramic		

Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage


2 Schäden




0 Schäden



Component		Damage	Comments
1	Fender / Back Left	Bodywork / Dent / Dent	
2	Tailgate	Paint / Poor Previous Repair	



1. Fender / Back Left
Bodywork / Dent / Dent -



2. Tailgate
Paint / Poor Previous Repair -

Mechanical Condition

Control Lights

ABS Warning Light	✓	Airbag Warning Light	✓
Brake Warning Light	✓	Alternator / Battery	✓
All - wheel Drive	✓	No Dashboard Lights	✓
Service Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Oil Pressure Warning Light	✓
Power Steering Warning Light	✓	Tire Pressure Monitoring System	✓

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓	Other Equipments	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Brake			
Brake System Anomaly		✓	
Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Clutch			
Clutch Functioning		✓	
General			

Test Driven Status NA

- ✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage
- ! Damages or malfunction detected that requires repairs by the buyer
- NA Not applicable
- ⊠ Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)