



AUDI Q5 I 2013 Diesel
Q5 2.0 tdi Business quattro 177cv s-tronic

VIN NO WAUZZZ8R4DA075561
Registration Number EP528XY



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-05-22	-	-	121281 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2013-04-09	Italy

Inspection Report Summary

Customer	BCA Lodi	Report Number	P20250925113653
Inspection Date / Place	2025-09-25 / BCA Lodi	Cosmetic Grade	5


Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Gearbox Type	Sequential
Colour	Black	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive
Seat Colour	Black	No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	159

Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage	Normal Use	Imported	No
Manufacturer Warrenty			





Equipment

Central locking	Rear parking sensors	Digital Radio	Front parking sensors
Volante multifuncion	Remote adjusting wing mirrors	Cruise control	Trip Computer
Stability control	Power assisted steering	Alloys wheels	Electrically folding wing mirrors
Satellite navigation	Parcel Shef	Remote central locking	Traction control
Tyre Mobility Kit			


Wheels & Tyres

Mounted Tires


Tyre / Wheel Type	Summer	
	NEXEN NEXEN-N'FERA SPORT SUV	235/65//R17 - 108V / 2 mm
	NEXEN NEXEN-N'FERA SPORT SUV	235/65//R17 - 108V / 2 mm
	GOODYEAR GOODYEAR-EFFICIENTGRIP SUV	235/65//R17 - 104V / 2 mm
	GOODYEAR GOODYEAR-EFFICIENTGRIP SUV	235/65//R17 - 104V / 2 mm

Cosmetic Damage

27 Danni



6 Danni



Component		Damage	Comments
1	Seat / Front Left	Interior / Broken	
2	Seat / Front Left	Interior / Ripped	
3	Seat / Front Left	Interior / Ripped	
4	Dashboard / Front	Interior / Warning Light ON	
5	Dashboard / Front	Interior / Scratched	
6	Steering Wheel / Front	Interior / Worn - out	
7	Windshield / Front	Glass Break / Impact	
8	Hood	Bodywork / Dent / Hail Area	
9	Bumper / Front	Bodywork / Breakage	
10	Fender / Front Left	Bodywork / Dent	
11	Rim / Front Left	Out of Bodywork / Scratch	
12	Mirror Shell / Front Left	Bodywork / Breakage	

13	Door / Front Left	Bodywork / Dent
14	Door Handle / Front Left	Paint / Scratch / Line
15	Door / Back Left	Bodywork / Dent
16	Rim / Back Left	Out of Bodywork / Scratch
17	Fender / Back Left	Bodywork / Dent
18	Bumper / Back	Bodywork / Breakage
19	Bumper / Back	Bodywork / Breakage
20	Fog Light / Back Right	Glass Break
21	Tailgate	Bodywork / Dent
22	Back Light / Right	Glass Break
23	Fender / Back Right	Bodywork / Dent
24	Rim / Back Right	Out of Bodywork / Scratch
25	Door / Back Right	Bodywork / Dent
26	Door / Front Right	Bodywork / Dent
27	Mirror Repeater / Right	Glass Break
28	Mirror Shell / Front Right	Paint / Scratch / Line
29	Fender / Front Right	Bodywork / Dent
30	Rim / Front Right	Out of Bodywork / Scratch
31	Roof	Bodywork / Dent / Hail Area
32	Door Handle / Back Right	Paint / Scratch / Line
33	Door Handle / Back Left	Paint / Scratch / Line



1. Seat / Front Left
Interior / Broken -



2. Seat / Front Left
Interior / Ripped -



3. Seat / Front Left
Interior / Ripped -



4. Dashboard / Front
Interior / Warning Light ON -



5. Dashboard / Front
Interior / Scratched -



6. Steering Wheel / Front
Interior / Worn - out -



7. Windshield / Front
Glass Break / Impact -



8. Hood
Bodywork / Dent / Hail Area -




9. Bumper / Front
Bodywork / Breakage -



10. Fender / Front Left
Bodywork / Dent -



11. Rim / Front Left
Out of Bodywork / Scratch -



12. Mirror Shell / Front Left
Bodywork / Breakage -



13. Door / Front Left
Bodywork / Dent -



14. Door Handle / Front Left
Paint / Scratch / Line -



15. Door / Back Left
Bodywork / Dent -



16. Rim / Back Left
Out of Bodywork / Scratch -



17. Fender / Back Left
Bodywork / Dent -



18. Bumper / Back
Bodywork / Breakage -



19. Bumper / Back
Bodywork / Breakage -



20. Fog Light / Back Right
Glass Break -



21. Tailgate
Bodywork / Dent -



22. Back Light / Right
Glass Break -



23. Fender / Back Right
Bodywork / Dent -



24. Rim / Back Right
Out of Bodywork / Scratch -



25. Door / Back Right
Bodywork / Dent -



26. Door / Front Right
Bodywork / Dent -



27. Mirror Repeater / Right
Glass Break -



28. Mirror Shell / Front Right
Paint / Scratch / Line -



29. Fender / Front Right
Bodywork / Dent -



30. Rim / Front Right
Out of Bodywork / Scratch -



31. Roof
Bodywork / Dent / Hail Area -



32. Door Handle / Back Right
Paint / Scratch / Line -



33. Door Handle / Back Left
Paint / Scratch / Line -

Mechanical Condition

Engine			
Vehicle Start - up	✓	Engine Starts	✓
Engine Leak Visible	✓		
Clutch			
Clutch Functioning	✓		
Equipments Test			
Other Equipments	✓	AC / Heating System	✓
Levels			
Brakes Fluid	✓	Coolant Fluid	⚠

Test Drive Inspection

Other Checks			
Brakes	✓	Steering	✓
Suspension	⚠		
Gearbox			
Manual Gearbox	⚠		
General			
Test Driven Status	✓	Test Drive Comment	NAVIGATORE NON FUNZIONANTE.
Equipments Test			
Steering Noise / Anomaly	✓		
Engine			
Power Loss	✓	Fume Quantity	⚠
Engine Noise	⚠		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
⚠ Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			