



AUDI A3
A3 1.0 TFSI Sportback

VIN NO WAUZZZ8V1HA122869
Registration Number V1HA122869



MOT Date

2026-08-01

Last Service



Number of Owners

3

Last Service Mileage



Number of Keys

2

First Registration Date

2017-03-31

Odometer Reading

120157 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250926110915
Inspection Date / Place	2025-09-26 / BCA Neuss	Cosmetic Grade	5

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Black	Engine Size (cc)	999
Engine Size	1.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	schwarz	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	104
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

USB Socket	Alloys wheels	Bluetooth telephone interface	Heated wing mirrors
Remote central locking	Satellite navigation	Leather steering wheel	Rain sensitive windscreen wipers
Airbag Status	Anti-lock braking	Cruise control	Remote adjusting wing mirrors
Roof rails	Stability control	Radio	Rear parking sensors

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	16
Seat Heating	Front		

Wheels & Tyres


Right Rear Tyre Depth	5	Left Rear Tyre Depth	5
Right Front Tyre Depth	5	Left Front Tyre Depth	5

Cosmetic Damage

22 Schäden



0 Schäden



Component		Damage	Comments
1	Rim / Front Right	Out of Bodywork / Scratch	
2	Rim / Front Left	Out of Bodywork / Scratch	
3	Bumper / Front	Paint / Scratch / Scuff	
4	Bumper / Front	Paint / Scratch / Scuff	
5	Bumper / Front	Paint / Scratch / Scuff	
6	Bumper / Front	Paint / Scratch / Scuff	
7	Hood	Paint / Scratch / Scuff	
8	Hood	Bodywork / Dent / Dent	
9	Fender / Front Right	Paint / Scratch / Scuff	
10	Door / Back Right	Paint / Scratch / Scuff	
11	Door / Back Right	Paint / Scratch / Scuff	
12	Fender / Back Right	Paint / Scratch / Scuff	

13	Bumper / Back	Paint / Scratch / Scuff
14	Bumper / Back	Paint / Scratch / Scuff
15	Bumper / Back	Paint / Scratch / Scuff
16	Bumper / Back	Paint / Scratch / Scuff
17	Bumper / Back	Paint / Scratch / Scuff
18	Fender / Back Left	Bodywork / Dent / Dent
19	Fender / Back Left	Paint / Scratch / Scuff
20	Door / Back Left	Bodywork / Dent / Dent
21	Mirror / Front Left	Paint / Scratch / Scuff
22	Door / Front Left	Paint / Scratch / Scuff



1. Rim / Front Right
Out of Bodywork / Scratch -




2. Rim / Front Left
Out of Bodywork / Scratch -




3. Bumper / Front
Paint / Scratch / Scuff -




4. Bumper / Front
Paint / Scratch / Scuff -




5. Bumper / Front
Paint / Scratch / Scuff -



6. Bumper / Front
Paint / Scratch / Scuff -




7. Hood
Paint / Scratch / Scuff -




8. Hood
Bodywork / Dent / Dent -



9. Fender / Front Right
Paint / Scratch / Scuff -



10. Door / Back Right
Paint / Scratch / Scuff -



11. Door / Back Right
Paint / Scratch / Scuff -



12. Fender / Back Right
Paint / Scratch / Scuff -



13. Bumper / Back
Paint / Scratch / Scuff -



14. Bumper / Back
Paint / Scratch / Scuff -



15. Bumper / Back
Paint / Scratch / Scuff -



16. Bumper / Back
Paint / Scratch / Scuff -




17. Bumper / Back
Paint / Scratch / Scuff -




18. Fender / Back Left
Bodywork / Dent / Dent -




19. Fender / Back Left
Paint / Scratch / Scuff -



20. Door / Back Left
Bodywork / Dent / Dent -



21. Mirror / Front Left
Paint / Scratch / Scuff -



22. Door / Front Left
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Service Light	⚠
Tire Pressure Monitoring System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Electric Windows	✓	Navigation System	✓
AC / Heating System	✓	Main & Spare Keys Functioning	⚠
Parking Sensors / Cameras Functioning	✓		

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly ✓

Engine

Engine Noise ✓ The Gears Scratch / Skip / Abnormal Operation ✓

Fume Quantity ✓ Power Loss ✓

Brake

Brake System Anomaly ✓

Clutch

Clutch Functioning ✓

General

Test Driven Status ✓

- ✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage
- ! Damages or malfunction detected that requires repairs by the buyer
- NA Not applicable
- ☐ Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)