



# AUDI A3

## A3 2.0 TDI Sportback (clean die.) quattro S tronic

VIN NO WAUZZZ8V2GA173375

Registration Number V2GA173375



MOT Date

2026-01-01

Last Service



Number of Owners



2

Last Service Mileage



206534

Number of Keys



2

First Registration Date



2016-06-15

Odometer Reading



216629 km

Country First Registered



Germany

### Inspection Report Summary

Customer	BCA Online	Report Number	P20250820072555
Inspection Date / Place	2025-08-20 / BCA Heidenheim	Cosmetic Grade	1

### Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Grey	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	Dunkelgrau Blau	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	127
Gearbox Type	Automatic		

### Vehicle History & Documents


Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warranty			











### Equipment

Tinted Glass	USB Socket	Alloys wheels	Bi Xenon Headlamps
Diesel particulate filter	Front fog lamps	Headlamp wash/wipe	Remote adjusting wing mirrors
Roof rails	Split folding rear seats	CD Player	Radio
Trip Computer	Airbag Status	Anti-lock braking	Bluetooth telephone interface
Enhanced speaker system	Front parking sensors	Heated wing mirrors	Remote central locking
Satellite navigation	Stability control	Leather steering wheel	Rear parking sensors

### Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	18
Enhanced Speaker System	Bang&Olufsen	Seat Heating	Front

### Wheels & Tyres


Left Front Tyre Depth	1	Right Front Tyre Depth	1
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4

Cosmetic Damage

6 Schäden



2 Schäden



Component	Damage	Comments
1 Seat / Front Left	Interior / Worn - out	
2 Backrest Cover / Front Right	Interior / Scratched	
3 Tire / Front Left	Tire	
4 Hood	Bodywork / Dent / Dent	
5 Tire / Front Right	Tire	
6 Side Panel / Back Right	Bodywork / Dent / Dent	
7 Rim / Back Right	Out of Bodywork / Scratch	
8 Bumper / Back	Paint / Scratch / Scuff	






1. Seat / Front Left  
Interior / Worn - out -



2. Backrest Cover / Front Right  
Interior / Scratched -



3. Tire / Front Left  
Tire -



4. Hood  
Bodywork / Dent / Dent -



5. Tire / Front Right  
Tire -



6. Side Panel / Back Right  
Bodywork / Dent / Dent -





7. Rim / Back Right  
Out of Bodywork / Scratch -



8. Bumper / Back  
Paint / Scratch / Scuff -



## Mechanical Condition

### Control Lights

Display Defect	✓	ABS Warning Light	✓
ESP Fault/Traction Control Malfunction Light	✓	Diesel Particulate Filter Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	All - wheel Drive	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

### Equipments Test

Main & Spare Keys Functioning	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

### Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

### Gearbox

Gear Box	✓
----------	---

### Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Brake

Brake System Anomaly

General

Test Driven Status

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)