



AUDI A3

A3 1.4 TFSI Sportback

VIN NO WAUZZZ8V8GA018362
Registration Number V8GA018362



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-10-01	2	2	127572 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2024-02-22	108841	2015-07-16	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250918123559
Inspection Date / Place	2025-09-18 / BCA Oberndorf	Cosmetic Grade	3


Vehicle Summary



Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Red	Engine Size (cc)	1395
Engine Size	1.4	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	122
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	Alloys wheels	Bluetooth telephone interface	Front parking sensors
Remote adjusting wing mirrors	Satellite navigation	Sunroof	Leather steering wheel
Rear parking sensors	Airbag Status	Anti-lock braking	Front fog lamps
Heated wing mirrors	Remote central locking	Stability control	Xenon headlamps
Radio			

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	17
Seat Heating	Front	Sunroof Type	Opening Panoramic

Wheels & Tyres

Right Front Tyre Depth	6	Left Front Tyre Depth	6
Right Rear Tyre Depth	6	Left Rear Tyre Depth	6

Cosmetic Damage

11 Schäden




0 Schäden



Component		Damage	Comments
1	Rim / Front Right	Out of Bodywork / Scratch	
2	Rocker Panel / Center Right	Paint / Scratch / Scuff	
3	Window Cover / Back Left	Paint / Poor Previous Repair	
4	Hood	Paint / Poor Previous Repair	
5	Rim / Back Left	Out of Bodywork / Scratch	
6	Roof	Bodywork / Dent / Dent	
7	Door / Back Left	Bodywork / Dent / Dent	
8	Hood	Paint / Stone Chip	
9	Hood	Paint / Scratch / Scuff	
10	Bumper / Front	Paint / Scratch / Scuff	
11	Bumper / Front	Paint / Scratch / Scuff	



1. Rim / Front Right
Out of Bodywork / Scratch -



2. Rocker Panel / Center Right
Paint / Scratch / Scuff -




3. Window Cover / Back Left
Paint / Poor Previous Repair -




4. Hood
Paint / Poor Previous Repair -




5. Rim / Back Left
Out of Bodywork / Scratch -




6. Roof
Bodywork / Dent / Dent -



7. Door / Back Left
Bodywork / Dent / Dent -



8. Hood
Paint / Stone Chip -



9. Hood
Paint / Scratch / Scuff -



10. Bumper / Front
Paint / Scratch / Scuff -



11. Bumper / Front
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	!
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓		

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	!
Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	Fume Quantity	✓
Power Loss	✓		
Clutch			
Clutch Functioning	✓		
General			
Test Driven Status	Not Performed		
✓	No troubles detected, good condition or correct tests, according to vehicle age and mileage		
ⓘ	Damages or malfunction detected that requires repairs by the buyer		
NA	Not applicable		
⊞	Not tested		

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)