

INSPECTION REPORT



End Of Contract

GENERAL INFO

File	249912
License plate	1WFH228
Vehicle identification number	WAUZZZ8V8KA094530
Dossier	2019 081 002
Make	Audi A3SB 30 TFSi 85kW Design
Mileage	29327.00
First registration	20/05/2019
	19/11/2024

CHECK POINTS

Description	Number	Present	Remark
Certificate of conformity			
Registration certificate			
Charging cable			
Original license plate		Y	
Repair kit		Y	
Spare wheel			
RunOnFlat			
Keys	2	Y	
Towbar (+keys)			





DAMAGES

Damages	Type	Acceptable
201	Rocker Panel Right // Smart Repair Medium	N
192	Door Rear Right // Smart Repair Large	Y
236	Wing Front right // Polish	Y
240	Headlight / Front Right/ Repair	Y
16	Bumper Front // Polish	Y
222	Side View Mirror Right // Painting	N
645	Rear Right Door Interior Coating / Reflector / Replace	N
532	Trunk Compartment / Side Cover Left / Replace	Y
539	Trunk Compartment / Back Coating / Replace	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
159	Rear Bonnet / Rear Window / Replace	Y
174	Light / Rear Right / Replace	Y
133	Bumper Rear // Painting	N
116	Wing Rear Left // Polish	Y
91	Rocker Panel Left // Smart Repair Medium	Y
101	Door Rear Left // Smart Repair Medium	N
83	Door Front Left // Painting	N
72	Side View Mirror Left // Painting	Y

Damage Pictures



Wheel Alloy Front Left // Repair



Seat Rear Left // Repair



Front Bonnet // Painting



Wheel Alloy Front Right // Repair



Wheel Alloy Rear Right // Repair



Bumper Rear // Painting




Wheel Alloy Rear Left // Repair



Wing Front right // Painting



Bumper Front // Painting



Door Front Left // Repair & Painting



Wing Front Left // Painting