


Vehicle details

VIN	WAUZZZ8V9 LA072229	Brand	AUDI	Maintenance date	-
Licence Plate	H0-51-ZD	Model	A3 Limousine 35 TFSI S tronic Advance Sport 4d	Maintenance mileage	-
Registration date	25/06/2020	Year	2020	Exterior Color	Black Metallic
Odometer	231 418 km	Engine size	1498	interior Color	Grey
Fuel	Petrol	Body Type	Saloon / Hatchback	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	4	Gears	-		

Inspection Details

Inspection date	12/08/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Heating seats	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Mixed upholstery	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel kit	✓
-----------------	---

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Hankook 225/40/19 Summer 7.0 mm			Hankook 225/40/19 Summer 7.0 mm	
Hankook 225/40/19 Summer 7.5 mm			Hankook 225/40/19 Summer 7.5 mm	

Exterior

1



Part

Bonnet

Position

-

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Smart Repair

●

●

2



Part

Bumper

Position

Front

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

●

●

3



Part

Spoiler

Position

Front

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

4



Part

Alloy wheel 18"

Position

Front right

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair

●

●

5



Part

Alloy wheel 18"

Position

Back right

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair

●

●

6



Part

Tailgate / Boot door

Position

-

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

7



Part

Bumper

Position

Back

Damages

Scratched

Severity

Length (cm) > 10

Repair mode

Repair

●

●

●

8



Part

Alloy wheel 18"

Position

Back left

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair

●

●

9



Part

Door

Position

Back left

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Smart Repair

●

●

10



Part

Alloy wheel 18"

Position

Front left

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair

●

●