

INSPECTION REPORT


End Of Contract

GENERAL INFO

File	287787
License plate	1XQL639
Vehicle identification number	WAUZZZF21LN071674
Dossier	2019364282
Make	Audi A6 Av.30 TDi Bus.Ed.Str.
Mileage	112011
First registration	09/03/2020
client availability date	08/07/2025
inspectionDate	09/07/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
14	Bumper Front // Repair & Painting	N
61	Wing Front Left // Smart Repair Medium	N
801	See External Expertise	N
72	Side View Mirror Left // Painting	N
134	Bumper Rear // Repair & Painting	Y
320	Wheel Two Tone Rear Left // Repair	Y
340	Wheel Two Tone Front Right // Repair	Y

Damage Pictures



Side View Mirror Left // Painting-scratch



Bumper Rear // Repair & Painting-scratch + dent



Wheel Two Tone Rear Left // Repair-Chemical reaction



Wheel Two Tone Front Right // Repair-Chemical reaction



Wing Front Left // Smart Repair Medium-scratch



Bumper Front // Repair & Painting-scratch + dent



See External Expertise-