



AUDI A6  
A6 Avant 50 TDI quattro tiptronic

VIN NO WAUZZZF23LN105064  
Registration Number 23LN105064



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	1	2	235814 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2020-10-06	-

Inspection Report Summary

Customer	BCA Online	Report Number	P20250923145210
Inspection Date / Place	2025-09-23 / BCA Berlin	Cosmetic Grade	1

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Diesel	Road Worthy	Yes
Colour	Grey	Engine Size (cc)	2967
Engine Size	3.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Synthetic Leather
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			











Equipment

Tow ball	Trip Computer	Airbag Status	Ambientlighting
Anti-lock braking	Bluetooth telephone interface	Cruise control	Digital Radio
Enhanced speaker system	Heated wing mirrors	Remote central locking	Roof rails
Seatventilation	Sunroof	Electrically adjustable seats	Leather steering wheel
Radio	Rear parking sensors	Trafficsignrecognition	USB Socket
Alloys wheels	AndroidAuto	AppleCarPlay	Cabin Pre Heating
Diesel particulate filter	Digitaldashboard	Front parking sensors	Remote adjusting wing mirrors
Reversing Camera	Satellite navigation	Stability control	Distancewarningsystem
Electrically folding wing mirrors	LED Headlamps	Rain sensitive windscreen wipers	Rear sunblind

Equipment Details


Tow Ball Type	Pivoted	Air Conditioning	Four Zone Climate Control
Alloy Wheel Size	18	Seat Heating	Front and Rear
Sunroof Type	Opening Panoramic		

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

4 Schäden




2 Schäden



Component	Damage	Comments
1 Roof	Bodywork / Dent / Dent	
2 Hood	Bodywork / Dent / Dent	
3 Bumper / Front	Paint / Scratch / Scuff	
4 Mirror Repeater / Right	Glass Break	
5 Luggage Space Cover / Back	Interior / Worn - out	
6 Luggage Space Cover / Back	Interior / Worn - out	






1. Roof  
Bodywork / Dent / Dent -



2. Hood  
Bodywork / Dent / Dent -




3. Bumper / Front  
Paint / Scratch / Scuff -



4. Mirror Repeater / Right  
Glass Break -



5. Luggage Space Cover / Back  
Interior / Worn - out -



6. Luggage Space Cover / Back  
Interior / Worn - out -

## Mechanical Condition

### Equipments Test

Central Locking	❗	Electric Windows	✓
Audio Equipment	✓	AC / Heating System	✓
Main & Spare Keys Functioning	✓	Navigation System	✓
Parking Sensors / Cameras Functioning	✓	Other Equipments	✓

### Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
All - wheel Drive	✓	No Dashboard Lights	❗
Display Defect	✓	Service Light	✓
Tire Pressure Monitoring System	✓		

### Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

### Gearbox

Gear Box	✓
----------	---

### Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---



Test Drive Inspection

Steering Wheel			
Steering   Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)