



Vehicle details

VIN	WAUZZZF23 NN063000	Brand	AUDI	Maintenance date	-
Licence Plate	W28331M	Model	A6 40 Tdi Quattro S Tronic Sport Avant 150K	Maintenance mileage	-
Registration date	30/06/2022	Year	1000	Exterior Color	Black Metallic
Odometer	125 909 km	Engine size	1968	interior Color	Black
Fuel	Diesel	Body Type	Estate	Next technical inspection	01/06/2027
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	25/11/2025	Inspection loc.	Hödlmayr Logistics GmbH
-----------------	------------	-----------------	-------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
GPS system	✓
Xenon projectors	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Heating seats	✓


Removable element

--

Technical Document

Service manual holder	✓
User manual	✓
Spare key	✓
Remote key	✓

Tyres



Continental 225/55/18 V Summer 3.4 mm

Continental 225/55/18 V Summer 3.2 mm

Continental 225/55/18 V Summer 4.8 mm

Continental 225/55/18 V Summer 4.6 mm

Exterior



1		<table border="1"> <tr><td>Part</td><td>Windscreen</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>Stone impact</td></tr> <tr><td>Severity</td><td>Diameter (mm) > 10</td></tr> <tr><td>Repair mode</td><td>Replace</td></tr> </table>	Part	Windscreen	Position	-	Damages	Stone impact	Severity	Diameter (mm) > 10	Repair mode	Replace	2		<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Front</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Bumper	Position	Front	Damages	Scratched	Severity	-	Repair mode	Repair
Part	Windscreen																								
Position	-																								
Damages	Stone impact																								
Severity	Diameter (mm) > 10																								
Repair mode	Replace																								
Part	Bumper																								
Position	Front																								
Damages	Scratched																								
Severity	-																								
Repair mode	Repair																								
4		<table border="1"> <tr><td>Part</td><td>Bumper</td></tr> <tr><td>Position</td><td>Back</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Repair</td></tr> </table>	Part	Bumper	Position	Back	Damages	Scratched	Severity	-	Repair mode	Repair	5		<table border="1"> <tr><td>Part</td><td>Wing</td></tr> <tr><td>Position</td><td>Back right</td></tr> <tr><td>Damages</td><td>Dented</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </table>	Part	Wing	Position	Back right	Damages	Dented	Severity	-	Repair mode	For info
Part	Bumper																								
Position	Back																								
Damages	Scratched																								
Severity	-																								
Repair mode	Repair																								
Part	Wing																								
Position	Back right																								
Damages	Dented																								
Severity	-																								
Repair mode	For info																								
6		<table border="1"> <tr><td>Part</td><td>Exterior door mirror shell</td></tr> <tr><td>Position</td><td>Right</td></tr> <tr><td>Damages</td><td>Scratched</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>For info</td></tr> </table>	Part	Exterior door mirror shell	Position	Right	Damages	Scratched	Severity	-	Repair mode	For info													
Part	Exterior door mirror shell																								
Position	Right																								
Damages	Scratched																								
Severity	-																								
Repair mode	For info																								

Interior damage

3		<table border="1"> <tr><td>Part</td><td>Fabric door lining</td></tr> <tr><td>Position</td><td>Back left</td></tr> <tr><td>Damages</td><td>Deformed</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Replace</td></tr> </table>	Part	Fabric door lining	Position	Back left	Damages	Deformed	Severity	-	Repair mode	Replace			
Part	Fabric door lining														
Position	Back left														
Damages	Deformed														
Severity	-														
Repair mode	Replace														

Others

7		<table border="1"> <tr><td>Part</td><td>Paint preparation</td></tr> <tr><td>Position</td><td>-</td></tr> <tr><td>Damages</td><td>-</td></tr> <tr><td>Severity</td><td>-</td></tr> <tr><td>Repair mode</td><td>Plastic paint</td></tr> </table>	Part	Paint preparation	Position	-	Damages	-	Severity	-	Repair mode	Plastic paint			
Part	Paint preparation														
Position	-														
Damages	-														
Severity	-														
Repair mode	Plastic paint														