

WAUZZZF24NN060963

AUDI A6 A6 Avant 40 TDI quattro S tronic



## TECHNICAL CONDITION

| Engine                       | Brakes                                                                         | Steering                                                              |
|------------------------------|--------------------------------------------------------------------------------|-----------------------------------------------------------------------|
| Engine starts                | Brake operation                                                                | Sounds normal                                                         |
| Engine operation             | <b>Clutch</b><br>Clutch operation<br>Idle sounds normal<br>Clutch biting point | <b>Gear Box</b><br>Automatic shift<br>Manual shif<br>Warning light OK |
| Engine compartment dry (oil) |                                                                                |                                                                       |
| Fume quantity                |                                                                                |                                                                       |
| Sounds normal                |                                                                                |                                                                       |

## COMPLAINT NOTE

The technical check includes a visual check of the vehicles without removal of any components.  
The condition of the mechanical components cannot be rated.

## LEVELS

|               |  |
|---------------|--|
| Coolant fluid |  |
| Brakes fluid  |  |

## EQUIPMENT TEST

|                          |  |
|--------------------------|--|
| Electric windows test    |  |
| Audio equipment          |  |
| Navigation equipment     |  |
| AC / Heating system      |  |
| Central lock system test |  |

## TYRES

|                |      |    |      |
|----------------|------|----|------|
| Profile depths |      |    |      |
| FL             | 5 mm | FR | 5 mm |
| BR             | 5 mm | BL | 5 mm |

## Additional tyre profil depths

|   |      |   |      |
|---|------|---|------|
| A | 5 mm | B | 5 mm |
| C | 5 mm | D | 5 mm |

## CONTROL LIGHTS

|                                            |  |
|--------------------------------------------|--|
| Dashboard                                  |  |
| ABS                                        |  |
| Oil                                        |  |
| Airbag                                     |  |
| Engine                                     |  |
| Brakes                                     |  |
| Steering                                   |  |
| DPF                                        |  |
| Diesel heaters                             |  |
| Traction control / ESP / Stability control |  |
| 4x4                                        |  |
| Alternator / Battery                       |  |



No defects recognizable, good condition or positive tests based on vehicle's age and mileage.



Registered damage that needs to be repaired by the buyer.



Not verifiable.