



Audi A6 (MKL): 1YFT881

Vinnumber:	WAUZZZF26KN119698	Versionname:	A6 Avant Business Edition Sport 35 2.0TDI 163pk 5p S-Tronic
First Registrationdate:	18/08/2020	Fiscalpower:	
Expertise Mileage:	174495	Power Kw:	120
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Battery functioning	Yes		
Registration Certificate Car (BE)	Yes		
Maintenance	23800.0		
Maintenance	augustus 2027		

Options

Type of Maintenance book	Digital maintenance	Luggage cover	
Type of GPS storage	HD	Type of Tow bar	No Tow bar
GPS			
Number of keys total	2		

Tyres

Tyre size RL	225/55 R 18 98 V
Tyre type FL	Summer
Tyre type RL	Summer
Tyre profile depth FR	4.0
Tyre profile depth RR	6.0
Tyre size FR	225/55 R 18 102 Y
Tyre make FR	255

225/55/18/102 Y

Summer tyres:	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Firestone: 6 mm	Re.R.	Firestone: 6 mm

Tyre size RR	225/55 R 18 98 V
Tyre make RR	258
Tyre profile depth FL	3.0
Tyre size FL	225/55 R 18 102 Y
Tyre make FL	255
Tyre profile depth RL	6.0
Tyre type FR	Summer
Tyre type RR	Summer
Tyre make RL	258

Assistance equipment

Number of charging cables (normal)	0	Compressor	Yes
Number of charging cables (rapid charge)	0		
Repair kit	Yes		

Backrest cover FL, Worn, Acceptable



Interior, Dirty, Forfeit



Cigar lighter, Missing, Forfeit



Door panel RR, Scratch(es), Smart repair



Bumper F, Scratch(es), Repair and paint (complete)



Alloy rim FL, Scratch(es), Repair and paint (complete)



Wing FL, Scratch(es), Acceptable



Door RL, Scratch(es), Acceptable



Step L, Scratch(es), Acceptable



Alloy rim RL, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Luggage compartment cover, Scratch(es), Acceptable



Internal boot lining L, Scratch(es), Acceptable



Internal boot lining R, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Replace



Bumper R, Scratch(es), Repair and paint (complete)




Alloy rim FR, Scratch(es), Acceptable



Outside rear-view mirror housing R, Scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Acceptable



Alloy rim RR, Scratch(es), Acceptable

