



AUDI A6

A6 Avant 40 TDI quattro S tronic

VIN NO WAUZZZF28PN000879
Registration Number 28PN000879



MOT Date

2025-09-01

Last Service

2025-08-11

Number of Owners

1

Last Service Mileage

150811

Number of Keys

1

First Registration Date

2022-09-06

Odometer Reading

150830 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250925133718
Inspection Date / Place	2025-09-25 / BCA Oberndorf	Cosmetic Grade	1


Vehicle Summary


Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Diesel	Road Worthy	Yes
Colour	White	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz/grau	Seat Covering	Cloth/Leather
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	Trafficsignrecognition	USB Socket	Alloys wheels
AndroidAuto	AppleCarPlay	Cruise control	Digital Radio
Front parking sensors	Remote adjusting wing mirrors	Roof rails	Split folding rear seats
Central locking	Electrically folding wing mirrors	Emergencybrakeassist	Leather steering wheel
Radio	Tow ball	Trip Computer	Airbag Status
Ambientlighting	Anti-lock braking	Bluetooth telephone interface	Diesel particulate filter
Digitaldashboard	Heated wing mirrors	Remote central locking	Satellite navigation
Stability control	Distancewarningsystem	Electrictailgate	Laneassist
LED Headlamps	Rear parking sensors		

Equipment Details


Tow Ball Type	Pivoted	Air Conditioning	Four Zone Climate Control
Alloy Wheel Size	19	Seat Heating	Front

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	6	Left Rear Tyre Depth	6

Cosmetic Damage

2 Schäden



1 Schäden



Component		Damage	Comments
1	Other	Anomalyon Element	
2	Bumper / Front	Paint / Scratch / Scuff	
3	Trunk Upholstery / Back	Interior / Scratched	



1.
Anomaly Element -



2. Bumper / Front
Paint / Scratch / Scuff -



3. Trunk Upholstery / Back
Interior / Scratched -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
All - wheel Drive	✓	No Dashboard Lights	✓
Tire Pressure Monitoring System	✓		

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓	Other Equipments	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		Not Performed	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i> ❗ <i>Damages or malfunction detected that requires repairs by the buyer</i> NA <i>Not applicable</i> ☐ <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

User Guide