



Audi A6 (MKL+): 1XAG527

Vinnnumber:	WAUZZZF29LN032699	Versionname:	A6 Avant Business Edition Sport 35 2.0TDi 163pk 5p S-Tronic
First Registrationdate:	24/10/2019	Fiscalpower:	
Expertise Mileage:	149622	Power Kw:	120
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	25300.0		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

225/55/18/102 V				
Winter tyres:	Fr.L.	Firestone: 6 mm	Fr.R.	Firestone: 6 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				225/55 R 18 102 V
Tyre size FR				225/55 R 18 102 V
Tyre size RL				225/55 R 18 102 V
Tyre size RR				225/55 R 18 102 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				258
Tyre make FR				258
Tyre make RL				256
Tyre make RR				256

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Ignition key, Not functioning (well), Acceptable



Interior, Damaged, Acceptable



Bonnet, Stone chip(s), Acceptable



Bumper F, Scratch(es), Spot repair



Bumper spoiler F, Scratch(es), Spot repair



Wing RL, Dent(s), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Bumper R, Dent(s) and scratch(es), Acceptable



Bumper moulding R, Broken, Replace



Step R, Dent(s) and scratch(es), Acceptable



Outside rear-view mirror housing R, Scratch(es), Acceptable



Tyres, Not original part, Forfeit



Bodywork, Damaged, Acceptable

