



AUDI A6
A6 Avant 45 TDI quattro S tronic

VIN NO WAUZZZF2XNN047151
Registration Number 2XNN047151



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2027-06-01	1	2	162921 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2025-03-25	141434	2022-06-20	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250922113421
Inspection Date / Place	2025-09-22 / BCA Oberndorf	Cosmetic Grade	3

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Diesel	Road Worthy	Yes
Colour	White	Engine Size (cc)	2967
Engine Size	3.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth/Synthetic Leather
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			









Equipment

Tinted Glass	USB Socket	Alloys wheels	Bluetooth telephone interface
Diesel particulate filter	Front parking sensors	Remote adjusting wing mirrors	Roof rails
Split folding rear seats	Electrically folding wing mirrors	Leather steering wheel	Radio
Tow ball	Airbag Status	Anti-lock braking	Cruise control
Digital Radio	Heated wing mirrors	Remote central locking	Satellite navigation
Stability control	Electric tailgate	LED Headlamps	Rear parking sensors

Equipment Details


Tow Ball Type	Pivoted	Air Conditioning	Four Zone Climate Control
Alloy Wheel Size	19	Seat Heating	Front

Wheels & Tyres


Left Rear Tyre Depth	7	Right Front Tyre Depth	5
Left Front Tyre Depth	5	Right Rear Tyre Depth	7

Cosmetic Damage

5 Schäden



2 Schäden



Component	Damage	Comments
1 Seat / Front Left	Interior / Scratched	
2 Tailgate Upholstery / Back	Interior / Scratched	
3 Fender / Front Right	Paint / Poor Previous Repair	
4 Door / Front Right	Paint / Poor Previous Repair	
5 Side Panel / Back Right	Paint / Poor Previous Repair	
6 Bumper / Front	Paint / Scratch / Scuff	
7 Mirror Shell / Front Right	Paint / Scratch / Scuff	



1. Seat / Front Left
Interior / Scratched -



2. Tailgate Upholstery / Back
Interior / Scratched -



3. Fender / Front Right
Paint / Poor Previous Repair -



4. Door / Front Right
Paint / Poor Previous Repair -



5. Side Panel / Back Right
Paint / Poor Previous Repair -



6. Bumper / Front
Paint / Scratch / Scuff -



7. Mirror Shell / Front Right
Paint / Scratch / Scuff -

Mechanical Condition

Equipments Test

Central Locking	✓	Electric Windows	✓
Navigation System	✓	Audio Equipment	✓
AC / Heating System	✓	Main & Spare Keys Functioning	✓
Parking Sensors / Cameras Functioning	✓		

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Display Defect	✓
Service Light	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	NA
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Test Drive Inspection

Steering Wheel

Steering Noise / Anomaly	✓
----------------------------	---

Engine

Engine Noise	✓	Fume Quantity	✓
Power Loss	✓		

General

Test Driven Status	Not Performed
--------------------	---------------

- ✔ *No troubles detected, good condition or correct tests, according to vehicle age and mileage*
- ❗ *Damages or malfunction detected that requires repairs by the buyer*
- NA *Not applicable*
- ☐ *Not tested*

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)