



AUDI Q3 Sportback

Q3 40 TFSI Sportback quattro S tronic

VIN NO WAUZZZF30R1009966
Registration Number 30R1009966



MOT Date

2026-09-01

Last Service



Number of Owners

1

Last Service Mileage



Number of Keys

2

First Registration Date

2023-09-05

Odometer Reading

22468 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250930141253
Inspection Date / Place	2025-09-30 / BCA Neuss	Cosmetic Grade	2



Vehicle Summary



Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Petrol	Gearbox Type	Automatic
Colour	Grey	Engine Size (cc)	1984
Engine Size	2.0	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	anthrazit	Seat Covering	Cloth/Synthetic Leather
Charging Cables		WLTP CO2 Emissions	

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	Airbag Status	Anti-lock braking	Bluetooth telephone interface
Digital Radio	Enhanced speaker system	Heated wing mirrors	Remote central locking
Satellite navigation	Sunroof	Electric tailgate	LED Headlamps
Rear parking sensors	USB Socket	Alloys wheels	AppleCarPlay
Cruise control	Digital dashboard	Front parking sensors	Remote adjusting wing mirrors
Reversing Camera	Stability control	Electrically folding wing mirrors	Leather steering wheel
Rain sensitive windscreen wipers			

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	19
Enhanced Speaker System	Sonos	Seat Heating	Front
Sunroof Type	Opening Panoramic		

Wheels & Tyres

Left Rear Tyre Depth	5	Right Front Tyre Depth	5
Left Front Tyre Depth	5	Right Rear Tyre Depth	5

Cosmetic Damage


2 Schäden



0 Schäden



Component		Damage	Comments
1	Door / Front Right	Bodywork / Dent / Dent	
2	Fender / Front Right	Bodywork / Dent / Dent	



1. Door / Front Right
Bodywork / Dent / Dent -



2. Fender / Front Right
Bodywork / Dent / Dent -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	All - wheel Drive	✓
No Dashboard Lights	✓	Display Defect	✓
Service Light	✓	Tire Pressure Monitoring System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	Main & Spare Keys Functioning	✓
Parking Sensors / Cameras Functioning	✓		

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)