

Inspection Protocol



AUDI Q3 40 TDI QUATTRO 2.0 TDI QUATTRO

Vehicle information

License plate	SUD26S	Inspected by	T.H.
Year model	2022	Date of inspection	2025-04-11
Manuf. year/month	2021-10	City	Björkvik
First day in traffic	2021-10	Keys	1
Colour	SVARTMETALLIC	Service book	Elektronisk servicebok
Mileage	141 360 km	Latest service	-
Fuel	Diesel	Mileage at the latest service	-
Transmission	S Tronic	Summer tires	18" alu-fälg 6/6/6/6
Engine effect	147 kW	Winter tires	alu-fälg odubbat 6/6/6/6

Damages

Location	Damage	Comments	Costs excluding VAT
Keys	Extra key missing		230 €
Bumper, Rear	Cargo scratches		180 €
Bumper, Front	Wide scratch		300 €
Wing, Front left	Scratches below 30 mm		70 €
Glass, Windshield	Chip		30 €

Total excl. VAT	810 €
-----------------	-------

Images

[See all images in large format](#)





















Stötfångare Bak Lastrepör 2 000 kr





Stötfångare Fram Skrap 3 300 kr



Skärm Vänster fram Repor under 3 cm 800 kr



Glas Vindruta Stenskott 300 kr