



AUDI Q3

Q3 45 TFSI S tronic

VIN NO WAUZZZF37N1131489
Registration Number 37N1131489



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2027-06-01	1	2	84947 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2025-06-05	83152	2022-06-13	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250930142856
Inspection Date / Place	2025-09-30 / BCA Neuss	Cosmetic Grade	2

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Plug - in Hybrid Electric Vehicle Petrol	Road Worthy	Yes
Colour	White	Engine Size (cc)	1395
Engine Size	1.4	No of Doors	5
Body Type	SUV	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	schwarz	Seat Covering	Cloth
Charging Cables	OUC + Type 2	NEDC CO2 Rating (q/km)	41
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Computer Print Out Available	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Airbag Status	Anti-lock braking	Cruise control	Digitaldashboard
Front parking sensors	Remote adjusting wing mirrors	Reversing Camera	Satellite navigation
Electrically folding wing mirrors	Leather steering wheel	Radio	Alloys wheels
Bluetooth telephone interface	Digital Radio	Enhanced speaker system	Heated wing mirrors
Remote central locking	Roof rails	Stability control	Electrictailgate
LED Headlamps	Rear parking sensors		

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	17
Enhanced Speaker System	Sonos	Seat Heating	Front

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

1 Schäden



0 Schäden



Component		Damage	Comments
1	Door / Back Left	Paint / Scratch / Scuff	



1. Door / Back Left
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
All - wheel Drive	✓	Alternator / Battery	✓
No Dashboard Lights	!	Display Defect	✓
Tire Pressure Monitoring System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓		

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Hybrid/EV

Hybrid System Fault	✓
---------------------	---

Test Drive Inspection

Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly	✓		
Steering Wheel			
Steering Noise / Anomaly	✓		
General			
Test Driven Status	✓		
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
☐ Not tested			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)