



AUDI Q3 Sportback

Q3 45 TFSIe Sportback S tronic

VIN NO WAUZZZF37P1012893
Registration Number 37P1012893



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-08-01	1	2	102348 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2023-03-30	18070	2022-08-11	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250903094108
Inspection Date / Place	2025-09-03 / BCA Neuss	Cosmetic Grade	3

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Plug - in Hybrid Electric Vehicle Petrol	Road Worthy	Yes
Colour	Silver	Engine Size (cc)	1395
Engine Size	1.4	No of Doors	5
Body Type	SUV	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Beige	Seat Covering	Leather
Charging Cables	OUC + Type 2	NEDC CO2 Rating (q/km)	42
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Computer Print Out Available	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Airbag Status	Anti-lock braking	Cruise control	Digitaldashboard
Heated wing mirrors	Remote central locking	Stability control	Electrictailgate
LED Headlamps	Rear parking sensors	Alloys wheels	Bluetooth telephone interface
Digital Radio	Front parking sensors	Remote adjusting wing mirrors	Satellite navigation
Electrically folding wing mirrors	Leather steering wheel	Radio	

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	18
Extra Wheel / Tyre Set	Winter Tyres - Steel	Seat Heating	Front

Wheels & Tyres


Right Front Tyre Depth	3	Left Front Tyre Depth	3
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4
Extra Wheel - 1 Tyre Depth	5	Extra Wheel - 2 Tyre Depth	5
Extra Wheel - 3 Tyre Depth	5	Extra Wheel - 4 Tyre Depth	5

Cosmetic Damage

10 Schäden



0 Schäden



	Component	Damage	Comments
1	Door / Back Left	Paint / Scratch / Scuff	
2	Roof	Bodywork / Dent / Dent	
3	Roof	Bodywork / Dent / Dent	
4	Roof	Bodywork / Dent / Dent	
5	Bumper / Back	Paint / Scratch / Scuff	
6	Tailgate	Paint / Scratch / Scuff	
7	Fender / Front Right	Paint / Scratch / Scuff	
8	Bumper / Front	Paint / Scratch / Scuff	
9	Hood	Bodywork / Dent / Dent	
10	Windshield / Front	Glass Break / Impact	




1. Door / Back Left
Paint / Scratch / Scuff -



2. Roof
Bodywork / Dent / Dent -



3. Roof
Bodywork / Dent / Dent -



4. Roof
Bodywork / Dent / Dent -



5. Bumper / Back
Paint / Scratch / Scuff -



6. Tailgate
Paint / Scratch / Scuff -



7. Fender / Front Right
Paint / Scratch / Scuff -



8. Bumper / Front
Paint / Scratch / Scuff -



9. Hood
Bodywork / Dent / Dent -



10. Windshield / Front
Glass Break / Impact -

Mechanical Condition

Control Lights

Display Defect	✓	ESP Fault/Traction Control Malfunction Light	✓
ABS Warning Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Tire Pressure Monitoring System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Electric Windows	✓	Navigation System	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

Hybrid/EV

Charge Lead Condition	✓	Charge Port Condition	✓
Hybrid System Fault	✓		

Levels

Brakes Fluid	✓	Coolant Fluid	⚠
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)