

INSPECTION REPORT




End Of Contract

GENERAL INFO

File	289879
License plate	2AXK411
Vehicle identification number	WAUZZZF38N1018716
Dossier	2021 134 032
Make	Audi Q3 35 TDi 110kW Bus.Ed.Ad
Mileage	145323
First registration	27/08/2021
client availability date	13/08/2025
inspectionDate	14/08/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
50	Headlight / Front left / Repair	N
66	Wing Front Left // Polish	Y
86	Door Front Left // Polish	Y
133	Bumper Rear // Painting	N
156	Rear Bonnet // Polish	Y
191	Door Rear Right // Smart Repair Medium	N
282	Bumper Rear / Trim Center / Replace	N
331	Wheel Alloy Rear Right // Repair	N


Damage Pictures



Door Rear Right // Smart Repair Medium-scratch



Wheel Alloy Rear Right // Repair-scratch



Rear Bonnet // Polish-scratch



Bumper Rear // Painting-scratch



Door Front Left // Polish-scratch



Wing Front Left // Polish-scratch



Bumper Rear / Trim Center / Replace-scratch + dent



Headlight / Front left / Repair-bad position