



Audi A4 (KKL): 1YJY628

Vinnumber:	WAUZZZF40MA001528	Versionname:	A4 Avant S-Line 30 2.0TDi 122pk/cv 5p
First Registrationdate:	16/09/2020	Fiscalpower:	
Expertise Mileage:	168984	Power Kw:	90
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	245/40/18/97 Y			
Summer tyres:	Fr.L.	Fulda: 5 mm	Fr.R.	Fulda: 5 mm
	Re.L.	Bridgestone: 6 mm	Re.R.	Bridgestone: 6 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				245/40 R 18 97 Y
Tyre size FR				245/40 R 18 97 Y
Tyre size RL				245/40 R 18 97 Y
Tyre size RR				245/40 R 18 97 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2484
Tyre make FR				2484
Tyre make RL				255
Tyre make RR				255

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Bumper F, Scratch(es), Acceptable



Bumper moulding F, Scratch(es), Acceptable



Wing FL, Scratch(es), Acceptable




Door RL, Dent(s), Paintless dent repair



Boot carpet, Chemical polution, Chemical cleaning



Boot lid covering R, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Alloy rim RR, Scratch(es), Repair and paint (complete)



Door RR, Bad repair, Repair and paint (complete)



Alloy rim FR, Scratch(es), Repair and paint (complete)



Door FR, Bad repair, Repair and paint (complete)

