

INSPECTION REPORT

End Of Contract

GENERAL INFO

File	285563
License plate	2ADB664
Vehicle identification number	WAUZZZF40MA046551
Dossier	2020 337 036
Make	Audi A4 Av.30 TDi Advan.Bus.Ed
Mileage	205377.00
First registration	25/02/2021
	16/06/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
13	Bumper Front // Painting	N
28	Front / Calendar / Replace	Y
41	Windshield // Replace	N
81	Door Front Left // Smart Repair Medium	Y
196	Door Rear Right // Polish	Y
234	Wing Front right // Repair & Painting	N
860	Interior Cleaning // Small	N

Damage Pictures



Wing Front right // Repair & Painting-scratch + dent



Door Rear Right // Polish-scratch



Door Front Left // Smart Repair Medium-scratch



Front / Calendar / Replace-cracked



Bumper Front // Painting-scratch



Windshield // Replace-glass damage



Interior Cleaning // Small-stain