



AUDI A4

A4 45 TFSI quattro S tronic

VIN NO WAUZZZF41KA069611
Registration Number 41KA069611



| | | | |
|--------------|----------------------|-------------------------|--------------------------|
| MOT Date | Number of Owners | Number of Keys | Odometer Reading |
| 2026-07-01 | 1 | 2 | 36041 km |
| Last Service | Last Service Mileage | First Registration Date | Country First Registered |
| - | - | 2019-04-16 | Germany |

Inspection Report Summary

| | | | |
|-------------------------|--|----------------|-----------------|
| Customer | BCA Online | Report Number | P20251007145247 |
| Inspection Date / Place | 2025-10-07 / SULOJA Mönchengladbach | Cosmetic Grade | 3 |

Vehicle Summary

| | | | |
|--------------------|-----------|------------------------|---------------------------|
| Vehicle Condition | Runner | VAT Type | Margin |
| Fuel Type | Petrol | Road Worthy | Yes |
| Colour | Black | Engine Size (cc) | 1984 |
| Engine Size | 2.0 | No of Doors | 4 |
| Body Type | Sedan | Drive Train | All-Wheel-Drive permanent |
| Seat Colour | | No of Seats | 5 |
| Seat Covering Name | | Seat Covering | Cloth/Leather |
| Charging Cables | | NEDC CO2 Rating (q/km) | 146 |
| Gearbox Type | Automatic | | |

Vehicle History & Documents

| | | | |
|------------------------|---------|----------------------|----|
| Service Book Available | Missing | Next Service Mileage | km |
| Previous Usage | | Imported | No |
| Manufacturer Warrenty | | | |







Equipment

| | | | |
|----------------------------------|-------------------------------|-----------------------------------|-------------------------|
| Tinted Glass | 360°camera | Alloys wheels | AndroidAuto |
| AppleCarPlay | Cabin Pre Heating | Digital Radio | Enhanced speaker system |
| Head up Display | Heated wing mirrors | Remote adjusting wing mirrors | Reversing Camera |
| Stability control | Electrically adjustable seats | Laneassist | LED Headlamps |
| Rear parking sensors | USB Socket | Airbag Status | Ambientlighting |
| Anti-lock braking | Bluetooth telephone interface | Cruise control | Digitaldashboard |
| Front parking sensors | Headlamp wash/wipe | Parking Assistance | Remote central locking |
| Satellite navigation | Central locking | Electrically folding wing mirrors | Leather steering wheel |
| Rain sensitive windscreen wipers | | | |

Equipment Details


| | | | |
|------------------------|----------------------|------------------|-------|
| Air Conditioning | Yes | Alloy Wheel Size | 18 |
| Extra Wheel / Tyre Set | Winter Tyres - Alloy | Seat Heating | Front |

Wheels & Tyres


| | | | |
|----------------------------|---|----------------------------|---|
| Extra Wheel - 1 Tyre Depth | 6 | Extra Wheel - 2 Tyre Depth | 6 |
| Extra Wheel - 3 Tyre Depth | 5 | Extra Wheel - 4 Tyre Depth | 5 |
| Right Front Tyre Depth | 4 | Left Front Tyre Depth | 4 |
| Right Rear Tyre Depth | 3 | Left Rear Tyre Depth | 3 |

Cosmetic Damage

1 Schäden



0 Schäden



| Component | Damage | Comments |
|------------------------------|----------------------------|----------|
| 1 Corner Bumper / Front Left | Bodywork / Breakage / Hole | |



1. Corner Bumper / Front Left
Bodywork / Breakage / Hole -

Mechanical Condition

Control Lights

| | | | |
|----------------------|---|--|---|
| ABS Warning Light | ✓ | ESP Fault/Traction Control Malfunction Light | ✓ |
| Airbag Warning Light | ✓ | Oil Pressure Warning Light | ✓ |
| Brake Warning Light | ✓ | Power Steering Warning Light | ✓ |
| Alternator / Battery | ✓ | All - wheel Drive | ✓ |
| No Dashboard Lights | ✓ | Service Light | ✓ |
| Display Defect | ✓ | | |

Engine

| | | | |
|---------------------|---|---------------------|---|
| Engine Status / EML | ✓ | Engine Leak Visible | ✓ |
| Engine Starts | ✓ | | |

Gearbox

| | |
|----------|---|
| Gear Box | ✓ |
|----------|---|

Levels

| | | | |
|--------------|---|---------------|---|
| Brakes Fluid | ✓ | Coolant Fluid | ✓ |
|--------------|---|---------------|---|

Equipments Test

| | | | |
|---------------------|---|---------------------------------------|---|
| Central Locking | ✓ | Main & Spare Keys Functioning | ✓ |
| Electric Windows | ✓ | Navigation System | ✓ |
| Audio Equipment | ✓ | Parking Sensors / Cameras Functioning | ✓ |
| AC / Heating System | ✓ | Other Equipments | ✓ |

Test Drive Inspection

| Engine | | | |
|----------------------------|---|---|---|
| Engine Noise | ✓ | The Gears Scratch / Skip / Abnormal Operation | ✓ |
| Fume Quantity | ✓ | Power Loss | ✓ |
| Brake | | | |
| Brake System Anomaly | ✓ | | |
| Steering Wheel | | | |
| Steering Noise / Anomaly | ✓ | | |
| General | | | |
| Test Driven Status | Not Performed | | |
| ✓ | No troubles detected, good condition or correct tests, according to vehicle age and mileage | | |
| ! | Damages or malfunction detected that requires repairs by the buyer | | |
| NA | Not applicable | | |
| ☐ | Not tested | | |

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)