

INSPECTION REPORT

End Of Contract


GENERAL INFO

File	288815
License plate	2APD303
Vehicle identification number	WAUZZZF42MA050553
Dossier	2020 288 003
Make	Audi A4 Av.35 TDi Advan.Bus.Ed
Mileage	148047
First registration	01/06/2021
client availability date	10/07/2025
inspectionDate	16/07/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
15	Bumper Front // Replace & Painting	N
31	Front Bonnet // Smart Repair Small	N
83	Door Front Left // Painting	Y
100	Door Rear Left // Smart Repair Small	N
133	Bumper Rear // Painting	Y
186	Wing Rear Right // Polish	Y
210	Door Front Right // Smart Repair Small	N
233	Wing Front right // Painting	N
341	Wheel Alloy Front Right // Repair	N
540	Interior // Repair 1	N
543	Interior // Ionization Odor	N
614	Front Left Door Interior Coating // Replace Completely	N

Damage Pictures



Wing Rear Right // Polish-scratch





Bumper Rear // Painting-scratch




Door Front Left // Painting-scratch




Wheel Alloy Front Right // Repair-scratch



Door Front Right // Smart Repair Small-dent



Door Rear Left // Smart Repair Small-dent



Front Bonnet // Smart Repair Small-scratch + dent



Bumper Front // Replace & Painting-scratch + dent



Interior // Repair 1-Incinerated



Front Left Door Interior Coating // Replace Completely-Incinerated



Wing Front right // Painting-Chemical reaction