

AUDI A4 AVANT				WAUZZZF42NA018588			
A4 Avant 30 TDi Business Ed.Advanced S tr.(EU6AP) 100 kw.							
X X X X X X X X X X X X X X X							
Km	165167	First use	09/02/2022	Summer RearRight Continental 225/0/17/50 4 mm Mounted FrontRight Continental 225/0/17/50 4 mm Mounted RearLeft Continental 225/0/17/50 4 mm Mounted FrontLeft Continental 225/0/17/50 4 mm Mounted			
Gearbox	Automatic	Drive system					
Doors	5	Seats	5				
Emission	Euro 6d	CO ₂	WLTP 130 gr/km				
Fuel type	Diesel	HP/kW	136 / 100				
Colour ext.	-	Colour int.	noir-noir / noir-noir / noir / gris Titane-zwart-z				
10d: Trailer hitch 220: Omission of model name and output/technology logo 4H5: Power-operated child safety lock 7UG: MMI navigation plus with MMI touch 9AQ: 3-zone deluxe automatic air conditioning C08: Operating permit, alteration IT3: Audi connect navigation & infotainment QL5: Privacy glass (dark-tinted windows) 1G5: Spare wheel, space-saving 3FU: Panoramic glass roof 4L6: Interior mirror, automatically dimming, frameless 7X2: Parking system plus 9JE: USB charging interface for rear seat passengers EB4: 1 year follow-on warranty, max. 120 000 km IU1: Audi smartphone interface QQ1: Ambient Lighting package 151: Vehicle tool kit and vehicle jack 3G4: ISOFIX child seat mounting for the front passenger seat 40F: Driver and front passenger airbag with front passenger airbag deactivation 8IT: LED headlights 959: Audi virtual cockpit plus FK2: AdBlue tank with increased capacity KA2: Reversing camera S25: Control (in-plant) 1XW: Leather steering wheel, 3-spoke with multifunction plus 4A3: Seat heating, front 6XX: Exterior mirrors, electrically adjustable, heated and folding, automatically dimming on both sides 8VM: LED rear combination lamps with dynamic turn signal 9VD: Audi sound system GPS Storage: N1F: Leather/mono-pur 550 artificial leather combination							
EN - pare-choc avant centre Broken				X X X X X X X			
EN - aile avant droit				X X X X X			
EN - porte avant gauche Scratch				X X X X X			
EN - pare-choc arrière centre Scratch				X X X X X X X X X			
Floor covering F L Hole				X X			
Alloy rim R L Scratch				X X X X			
Interior Dirty				X X X X X X X X X			
Air vent R M Broken				X X			

Interior	        
Damaged	

Bodywork	        
Damaged	