

# INSPECTION REPORT



**End Of Contract**

## GENERAL INFO

|                               |                               |
|-------------------------------|-------------------------------|
| File                          | 284646                        |
| License plate                 | 1XWX227                       |
| Vehicle identification number | WAUZZZF43LA068025             |
| Dossier                       | 2020024016                    |
| Make                          | Audi A4 Av.35 TDi Bus.Ed.Str. |
| Mileage                       | 162904.00                     |
| First registration            | 18/06/2020                    |
|                               | 17/06/2025                    |

## CHECK POINTS

| Description               | Number | Present | Remark |
|---------------------------|--------|---------|--------|
| Original license plate    |        | Y       |        |
| Registration Part 2       |        | N       |        |
| Keys                      | 1      | Y       |        |
| Spare wheel               |        | N       |        |
| Towbar (+keys)            |        | N       |        |
| Certificate of conformity |        | Y       |        |
| Registration certificate  |        | Y       |        |
| Repair kit                |        | Y       |        |
| RunOnFlat                 |        | N       |        |
| Charging cable            |        | N       |        |
| Charge back wrong tyres   |        | N       |        |





## DAMAGES

| Damages | Type                                             | Acceptable |
|---------|--------------------------------------------------|------------|
| 138     | Bumper Rear / Lower Cover Not Painted / Replace  | N          |
| 148     | Back Side / Reflector R / Replace                | N          |
| 13      | Bumper Front // Painting                         | N          |
| 134     | Bumper Rear // Repair & Painting                 | N          |
| 174     | Light / Rear Right / Replace                     | Y          |
| 183     | Wing Rear Right // Painting                      | N          |
| 233     | Wing Front right // Painting                     | N          |
| 335     | Wheel Rear Right / Hub Cover with Logo / Replace | N          |
| 883     | Key Price Range 2 //                             | N          |

## Damage Pictures



Wing Front right // Painting-scratch




Bumper Front // Painting-scratch



Wing Rear Right // Painting-scratch



Light / Rear Right / Replace-scratch



Bumper Rear // Repair & Painting-scratch



Wheel Rear Right / Hub Cover with Logo / Replace-missing



Bumper Rear / Lower Cover Not Painted / Replace-scratch + dent



Back Side / Reflector R / Replace-cracked