


Vehicle details

VIN	WAUZZZF44 KA114380	Brand	AUDI	Maintenance date	-
Licence Plate	ZT-34-6X	Model	A4 AVANT 35 TFSI 110kw S tronic sport Lease Editio	Maintenance mileage	-
Registration date	09/08/2019	Year	2019	Exterior Color	Black Metallic
Odometer	169 920 km	Engine size	1984	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	15/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Load cover	✓
------------	---

Technical Document

User manual	✓
Remote key	✓
Sat Nav CD ROM Software	✓
Spare key	✗

Tyres

Michelin 225/50/17 Summer 4.5 mm



Michelin 225/50/17 Summer 4.0 mm



Michelin 225/50/17 Summer 2.5 mm



Michelin 225/50/17 Summer 2.5 mm

Exterior

5



Part	Wing
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Repair

6




Part	Door
Position	Back left
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

7



Part	Alloy wheel 17"
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

8



Part	Roof post A/B/C
Position	Right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

9



Part	Step plate
Position	Back right
Damages	Scratched
Severity	-
Repair mode	For info

10



Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

11



Part	Door
Position	Back right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

12



Part	Door
Position	Front right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

13



Part	Alloy wheel 17"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

14



Part	Wing
Position	Front right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

15



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair

16



Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

Interior damage

1



Part	Spare key
Position	-
Damages	Missing
Severity	-
Repair mode	Replace

2



Part	Interior cleaning
Position	Front
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

3



Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

4



Part	Interior tailgate lining
Position	Up
Damages	Scratched
Severity	-
Repair mode	Replace