



AUDI A4

A4 Avant 40 TDI quattro S tronic

VIN NO WAUZZZF48NA051014

Registration Number 48NA051014



MOT Date

2025-07-01

Last Service

2025-08-18

Number of Owners

1

Last Service Mileage

-

Number of Keys

2

First Registration Date

2022-07-22

Odometer Reading

185965 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250818094512
Inspection Date / Place	2025-08-18 / BCA Heidenheim	Cosmetic Grade	2

Vehicle Summary



Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Diesel	Road Worthy	Yes
Colour	Grey	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth/Synthetic Leather
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		



Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warranty			









Equipment

Tinted Glass	Trip Computer	360°camera	Alloys wheels
Anti-lock braking	Cruise control	Digitaldashboard	Heated wing mirrors
Remote central locking	Roof rails	Split folding rear seats	Central locking
Electrictailgate	Keyless Entry	LED Headlamps	Rear parking sensors
Driver Seat Electrically adjustable	Tow ball	USB Socket	Airbag Status
AndroidAuto	Bluetooth telephone interface	Diesel particulate filter	Front parking sensors
Remote adjusting wing mirrors	Reversing Camera	Satellite navigation	Stability control
Electrically folding wing mirrors	Internet/Connectivity	Leather steering wheel	Radio
Rear sunblind			

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	19
Extra Wheel / Tyre Set	Winter Tyres - Alloy	Seat Heating	Front

Wheels & Tyres


Extra Wheel - 1 Tyre Depth	6	Extra Wheel - 2 Tyre Depth	6
Extra Wheel - 3 Tyre Depth	6	Extra Wheel - 4 Tyre Depth	6
Left Rear Tyre Depth	5	Right Rear Tyre Depth	5
Left Front Tyre Depth	4	Right Front Tyre Depth	4

Cosmetic Damage

4 Schäden



10 Schäden



Component		Damage	Comments
1	Seat / Front Left	Interior / Dirty	
2	Seat / Front Left	Interior / Worn - out	
3	Door Step / Front Left	Interior / Worn - out	
4	Other	Interior / Worn - out	
5	Other	Interior / Scraped	
6	Interior door handle Back right	Interior / Dirty	
7	Seat / Front Right	Interior / Worn - out	
8	Other	Interior / Scraped	
9	Other	Interior / Scraped	
10	Other	Interior / Scraped	
11	Hood	Paint / Stone Chip	
12	Rocker Panel / Center Right	Paint / Scratch / Scuff	

13	Other	Paint / Scratch / Scuff
----	-------	-------------------------


14	Other	Paint / Scratch / Scuff
----	-------	-------------------------



1. Seat / Front Left
Interior / Dirty -



2. Seat / Front Left
Interior / Worn - out -



3. Door Step / Front Left
Interior / Worn - out -



4.
Interior / Worn - out -



5.
Interior / Scraped -



6. Interior door handle Back right
Interior / Dirty -



7. Seat / Front Right
Interior / Worn - out -



8.
Interior / Scraped -



9.
Interior / Scraped -




10.
Interior / Scraped -




11. Hood
Paint / Stone Chip -



12. Rocker Panel / Center Right
Paint / Scratch / Scuff -



13.
Paint / Scratch / Scuff -



14.
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
All - wheel Drive	✓	No Dashboard Lights	✓
Display Defect	✓	Tire Pressure Monitoring System	!
Service Light	!		

Engine

Engine Status / EML	✓	Engine Starts	✓
Engine Leak Visible	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓
AC / Heating System	✓	Other Equipments	✓

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Engine			
Fume Quantity	✓	Engine Noise	✓
The Gears Scratch / Skip / Abnormal Operation	✓	Power Loss	✓
Brake			
Brake System Anomaly	✓		
Steering Wheel			
Steering Noise / Anomaly	✓		
Clutch			
Clutch Functioning	✓		
General			
Test Driven Status	✓		

- ✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage
- ! Damages or malfunction detected that requires repairs by the buyer
- NA Not applicable
- ☐ Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)