

INSPECTION REPORT


End Of Contract

GENERAL INFO

File	285084
License plate	1YEP676
Vehicle identification number	WAUZZZF56LA021757
Dossier	2020022080
Make	Audi A5 SB 30 TDi 100kW Bu.E.S
Mileage	94736.00
First registration	05/08/2020
	20/06/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
12	Bumper Front // Smart Repair Large	N
84	Door Front Left // Repair & Painting	Y
114	Wing Rear Left // Repair & Painting	N
180	Wing Rear Right // Smart Repair Small	Y
412	Seat Front Left / Bottom Coating / Replace	N
534	Trunk Compartment / Carpet / Replace	N

Damage Pictures



Bumper Front // Smart Repair Large-scratch




Seat Front Left / Bottom Coating / Replace-scratch



Wing Rear Right // Smart Repair Small-dent



Wing Rear Left // Repair & Painting-scratch + dent



Door Front Left // Repair & Painting-scratch + dent



Trunk Compartment / Carpet / Replace-cracked