



Audi A5 (KKL): 2BCD125

Vinnumber:	WAUZZZF59MA051448	Versionname:	A5 Sportback Bus. Advanced 35 2.0TDi 163pk/cv 5p S-Tronic
First Registrationdate:	25/05/2021	Fiscalpower:	
Expertise Mileage:	46476	Power Kw:	120
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	245/40/18/97 Y			
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				245/40 R 18 97 Y
Tyre size FR				245/40 R 18 97 Y
Tyre size RL				245/40 R 18 93 H
Tyre size RR				245/40 R 18 93 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				264
Tyre make FR				264
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Seat cover FL, Worn, Acceptable



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim FL, Scratch(es), Repair and paint (complete)



Wing FL, Scratch(es), Repair and paint (complete)



Door RL, Dent(s), Acceptable




Wing RL, Dent(s) and scratch(es), Acceptable



Alloy rim RL, Scratch(es), Repair and paint (complete)



Tyre RL, Tear, Replace



Boot lid covering R, Scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Acceptable



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)



Wheel aperture RR, Scratch(es), Spot repair



Alloy rim RR, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s), Acceptable



Sill trim R, Scratch(es), Repair and paint (complete)



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim FR, Scratch(es), Repair and paint (complete)

