



AUDI Q5 Sportback

Q5 50 TDI Sportback quattro tiptronic

VIN NO WAUZZZFY1N2073997
Registration Number Y1N2073997



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2025-06-01	1	2	92433 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2022-06-14	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250926114544
Inspection Date / Place	2025-09-26 / BCA Neuss	Cosmetic Grade	1

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Diesel	Road Worthy	Yes
Colour	White	Engine Size (cc)	2967
Engine Size	3.0	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name	schwarz	Seat Covering	Cloth
Charging Cables		WLTP CO2 Emissions	
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tinted Glass	Adaptivecruisecontrol	Alloys wheels	Anti-lock braking
Bluetooth telephone interface	Diesel particulate filter	Digitaldashboard	Front parking sensors
Heated wing mirrors	Remote central locking	Satellite navigation	Distancewarningsystem
Electrictailgate	Leather steering wheel	Radio	Rear sunblind
USB Socket	Airbag Status	AndroidAuto	AppleCarPlay
Cruise control	Digital Radio	Fatiguewarningsystem	Head up Display
Remote adjusting wing mirrors	Reversing Camera	Stability control	Electrically folding wing mirrors
Laneassist	LED Headlamps	Rear parking sensors	

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	19
Seat Heating	Front		

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

1 Schäden



0 Schäden



Component		Damage	Comments
1	Bumper / Back	Paint / Scratch / Scuff	



1. Bumper / Back
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
All - wheel Drive	✓	No Dashboard Lights	✓
Display Defect	✓	Service Light	✓
Tire Pressure Monitoring System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Electric Windows	✓	AC / Heating System	✓
Main & Spare Keys Functioning	⚠	Navigation System	✓
Parking Sensors / Cameras Functioning	✓		

Levels

Brakes Fluid	NA	Coolant Fluid	✓
--------------	----	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)