



Brand:	Audi	Mileage(km):	247553
Model:	Q5	Number of doors:	5
Model type:	2.0 TFSI quattro Sport S Line Edition Pano VC Stoelverwarming	Vehicle length (cm):	
License plate:	ZK494G	Vehicle width (cm):	
Report code:	9875	Vehicle height (cm):	
Chassis number:	WAUZZZF5J2189875	Vehicle body type:	
Type of vehicle:	Luxury	Traction:	Front+Rear
First int. reg.:	18/06/2019	Power(kw):	185
First NL reg.:	18/06/2019	Transmission:	Automatic
Color:	Grey <input checked="" type="checkbox"/> Metallic	Number of gears:	7
Weight (kg)(kg):	1795	Displacement(cc):	1984
Empty weight(kg):	1695	Number of cylinders:	4
Wheelbase (cm)(cm):	282	Fuel type:	Petrol
Top speed (km/h):	237	Fuel tank capacity:	
Cons. in the city (l/100 km):	8.4	EU category:	Euro 6
Cons. outside the city (l/100 km):	6.1	Energy label:	D
Average consumption (l/100 km):	7	NL Tax Rate %:	
Acceleration (s):	6.3	CO2 (g/km):	159
Cargo space (l):	1795	Nb. of Axles:	2
Perm. max weight (kg):	2400	APK date:	18/06/2025

opties

- | | | |
|--|--|---|
| <input checked="" type="checkbox"/> Alloy wheels | <input checked="" type="checkbox"/> LED rear lights | <input checked="" type="checkbox"/> Climate control |
| <input checked="" type="checkbox"/> Digital dashboard | <input checked="" type="checkbox"/> Exterior mirrors in car body color | <input checked="" type="checkbox"/> Climate control (analog) |
| <input checked="" type="checkbox"/> 4x4 performance | <input checked="" type="checkbox"/> Privacy glass | <input checked="" type="checkbox"/> Climate control (digital) |
| <input checked="" type="checkbox"/> Daytime running lights | <input checked="" type="checkbox"/> Rain sensor | <input checked="" type="checkbox"/> Climate control (L/R separated) |
| <input checked="" type="checkbox"/> Licht Sensor | <input checked="" type="checkbox"/> Rear wiper | <input checked="" type="checkbox"/> Large screen navigation |
| <input checked="" type="checkbox"/> bots waarschuwing systeem | <input checked="" type="checkbox"/> Rear parking sensors | <input checked="" type="checkbox"/> Keyless entry |
| <input checked="" type="checkbox"/> Anti-lock braking system | <input checked="" type="checkbox"/> Front parking sensors | <input checked="" type="checkbox"/> Keyless entry/start/stop |
| <input checked="" type="checkbox"/> ABS | <input checked="" type="checkbox"/> Rear-seat folding (equal parts) | <input checked="" type="checkbox"/> Keyless start/stop |
| <input checked="" type="checkbox"/> Airbag(s) | <input checked="" type="checkbox"/> Rear-seat folding (unequal parts) | <input checked="" type="checkbox"/> Electrically operated rear windows |
| <input checked="" type="checkbox"/> Audio | <input checked="" type="checkbox"/> Baggage separation net | <input checked="" type="checkbox"/> Electrically operated front windows |
| <input checked="" type="checkbox"/> bots herkenning systeem | <input checked="" type="checkbox"/> Luggage cover | <input checked="" type="checkbox"/> Electrically folding mirrors |
| <input checked="" type="checkbox"/> Central locking system | <input checked="" type="checkbox"/> Trunk opens electrically | <input checked="" type="checkbox"/> Electrically adjustable mirrors |
| <input checked="" type="checkbox"/> Start/stop system | <input checked="" type="checkbox"/> Aux connection | <input checked="" type="checkbox"/> Electrically heated driver's seat |
| <input checked="" type="checkbox"/> Power steering | <input checked="" type="checkbox"/> USB connection | <input checked="" type="checkbox"/> Electrically heated passenger seat |
| <input checked="" type="checkbox"/> Front seats adjustable in height | <input checked="" type="checkbox"/> Bluetooth streaming | <input checked="" type="checkbox"/> Central armrest front |
| <input checked="" type="checkbox"/> Multifunctional steering wheel | <input checked="" type="checkbox"/> Bluetooth car kit | <input checked="" type="checkbox"/> Sport seats |
| <input checked="" type="checkbox"/> Remote central locking | <input checked="" type="checkbox"/> Radio | <input checked="" type="checkbox"/> Extendable passenger seat |
| <input checked="" type="checkbox"/> Sports package (exterior) | <input checked="" type="checkbox"/> WiFi | <input checked="" type="checkbox"/> Extendable driver's seat |
| <input checked="" type="checkbox"/> Roof rail (silver) | <input checked="" type="checkbox"/> Cruise control | <input checked="" type="checkbox"/> Audio control on the steering wheel |
| <input checked="" type="checkbox"/> Metallic finish | <input checked="" type="checkbox"/> Sports package (interior) | <input checked="" type="checkbox"/> Leather sports steering wheel |
| <input checked="" type="checkbox"/> Panoramic roof (electrical) | <input checked="" type="checkbox"/> Black top interior | <input checked="" type="checkbox"/> Leather steering wheel |
| <input checked="" type="checkbox"/> LED headlights | <input checked="" type="checkbox"/> Airconditioning | <input checked="" type="checkbox"/> Switch flippers |
| <input checked="" type="checkbox"/> Headlight washers | <input checked="" type="checkbox"/> Airconditioning in the back | <input checked="" type="checkbox"/> Pedestrian safety system |

Tires

Tire position:	Tire type:	Wheel type:	Tire size:	Tire brand:	Tire profile depth (mm):
Tire left front	Summer	Alloy	235/55 R19	Continental	4
Tire left rear	Summer	Alloy	235/55 R19	Continental	5
Tire right front	Summer	Alloy	235/55 R19	Continental	4
Tire right rear	Summer	Alloy	235/55 R19	Continental	5

Additional information

No. of keys:	2 <input type="checkbox"/> Luxury key <input type="checkbox"/> Instruction booklet	<input checked="" type="checkbox"/> Airco works
Interior color:	Black Maintenance booklet:	<input checked="" type="checkbox"/> Odorless
Upholstery:	Half stof/leder	<input checked="" type="checkbox"/> Clean inside (Interior is clean)
No. of seats:	5 Stamp date:	<input checked="" type="checkbox"/> Display ok

No. of headrests:

5

Last turn mileage(km):

Vehicle special usage (None)

⚠ Cleaning

Clean inside (Interior is clean)

Clean outside

🔧 Damages

⊕ Not acceptable



Front left rim - Scratch



Rear right rim - Scratch



Windscreen - Pip



Bestuurderstoel slijtage

🔧 Damages

⊕ Acceptable

⚙ Extra options





