



Audi Q5 (MKL): 1YEQ092

Vinnumber:	WAUZZZF8L2019741	Versionname:	Q5 35 2.0TDi 163pk/cv 5p S-Tronic
First Registrationdate:	6/08/2020	Fiscalpower:	
Expertise Mileage:	188983	Power Kw:	120
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	14500.0		
Maintenance	615 dagen		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	235/65/17/108 V			
Summer tyres:	Fr.L.	Firestone: 3 mm	Fr.R.	Firestone: 3 mm
	Re.L.	Firestone: 3 mm	Re.R.	Firestone: 3 mm
Tyre profile depth FL				3.0
Tyre profile depth FR				3.0
Tyre profile depth RL				3.0
Tyre profile depth RR				3.0
Tyre size FL				235/65 R 17 108 V
Tyre size FR				235/65 R 17 108 V
Tyre size RL				235/65 R 17 108 V
Tyre size RR				235/65 R 17 108 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				258
Tyre make FR				258
Tyre make RL				258
Tyre make RR				258

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Interior, Dirty, Acceptable





Backrest cover FL, Scratch(es), Acceptable



Centre console, Hole, Forfeit



Door panel RL, Scratch(es), Smart repair




Engine, Not functioning (well), Check



Outside rear-view mirror base L, Scratch(es), Acceptable



Wing RL, Dent(s), Acceptable



Internal boot lining L, Scratch(es), Acceptable



Internal boot lining R, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Replace




Bumper R, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Repair and paint (complete)



Alloy rim RR, Scratch(es), Acceptable



Door RR, Scratch(es), Acceptable



Outer door handle RR, Scratch(es), Acceptable



Outside rear-view mirror base R, Broken, Replace



Mirror side repeater R, Broken, Replace

