


» Overview

Order number: 1002059422
Order completed: 20.08.2025 10:34
Report number: 8853634
VIN: WAUZZZFZ0NP044289



Front Left 3/4



Rear Right 3/4



Mileage

» Vehicle Data

Vehicle category:	Passenger Car
Vehicle type:	SUV
Make:	Audi
Model:	Q4
Manufacturers and type code:	0588 / BZS
Date of first registration:	28.06.2022
Mileage:	66,164 km
Exterior colour:	Noir Argent-Noir/Noir-Noir/Noir/Gris Acier
Roof colour:	Blanc Glacier Métallisé
Propulsion:	Front
Fuel:	Electric
Engine size (cc):	
Performance:	150 kW (205 PS)
Length:	4,588 mm
Height:	1,632 mm
Width:	1,865 mm
Permitted total weight:	2,640 kg
Wheelbase:	2,764 mm
Number of powered axles:	2
Cylinders:	
Euronorm:	
Number of doors:	5
Number of seats:	5
Gearbox:	Automatic 1-speed
Upholstery type:	Lining fabrics
Interior colour:	Blanc Glacier Métallisé
Number of keys:	2

» Documents & Maintenance

Statutory inspection date:	
Registration certificate available:	Yes
Registration certificate received:	Yes
License plate:	None
Maintenance book:	Digital
Maintenance:	Completed
Maintenance last date:	
Maintenance last mileage:	

» Standard Equipment

12-volt outlet(s)	Drum brakes in rear
3-point seat belts in front, with pretensioner/lap belt pretensioner and height adjustment	Electric motor unit 0EH.A
Accent surfaces painted in Matte Black	Electric motor, system output 125 kW base motor is N06/N07/N10/T3U
Acoustic vehicle alerting system	Electric opening/closing luggage compartment lid with sensor-controlled luggage compartment release
Additional front underbody guard	Electromechanical power steering
Adhesive film	Electronic immobilizer
Assistance package	Equipment 1
Assistance package	Equipment options subset for France
Audi AG	Exterior mirror housings in body color
Audi connect emergency call & service	Exterior mirrors, power-adjustable and heated
Audi connect remote & control for MMI basic	Exterior mirrors: aspherical on driver side, convex on front passenger side
Audi drive select	Fabric "Index"
Audi pre sense front	Floor mats, front and rear
Automatic air conditioning system	Front seats, manually adjustable
Basic	Front stabilizer bar
Basic	Functions-on-demand features not available
Battery 320 A (49 Ah)	Gear ratio 12.976
Bluetooth interface	Head restraints in front
Bumpers, basic	Headlining in cloth in specific color
Cell module A	High-Gloss Styling package
Charging cable for public charging, mode 3, 22 kW (AC)	High-voltage battery 55 kWh (gross) (net: 52 kWh)
Child-proof lock, electrically operated	Information kit in French
Clear glass	Inlay, Black paint finish
Comfort center armrest in front	Interior lighting
Comfort center armrest, front	Interior mirror, dimming
Comfort key without SAFELOCK	Interior with standard seats in Black fabric
Comfort stationary air conditioning	Internal control code
Comfort suspension	i-Size child seat mounting on the front passenger side and i-Size and top tether on the outer rear seats
Control of series production	Lane departure warning
Country group A	LED headlights
Coupe	LED rear lights
Cruise control with speed limiter	Left-hand drive
Daytime running light control	License plate carrier in front and rear (ECE)
DC battery charging (type 2)	Loudspeakers, front (passive)
DC-DC converter 3.0 kW	MMI
Digital Audio Broadcasting	Model name and technology logo
Digital instrument cluster	No special edition
Disk brakes, front, 18-inch	No special purpose vehicle, standard equipment
Drive system BEV	Non-smoker's package
Driver and front passenger airbag with front passenger airbag deactivation	On-board charger up to 7.2 kW (AC)
Driving on the right	

Operating permit, alteration	Visual and acoustic seat belt reminder, electric contact in front and rear
Parking aid Plus	Weight range 7 installation control only, no requirement forecast
Part set without country-specific prescriptive standard	Wheels, 5-arm, 8.0J x 19, 235/55!255/50 R19 tires
Platform group class 2	Windshield with heat-reflecting glass
Production wheels	With special labels safety certificates for France
Rear and side windows with heat-insulating glazing	Without additional tires
Rear seat backrest, folding	Without aluminum look in the interior
Rear stabilizer bar	Without antenna amplifier
Rear-wheel drive	Without Audi connect navigation & infotainment
Refrigerant R1234yf	Without Audi pre sense basic and pre sense rear
Regional code " ECE " for radio	Without camera systems/accident sensors
Safety package	Without camera-based traffic sign recognition
Service indicator 2 years (fix) without km, electric vehicle	Without Car2X
Shock absorption in front	Without charging cable (industrial connector)
Side airbags in front with curtain airbag system and center airbag in front	Without charging system
Single-tone horn	Without Climate Control package
Smartphone interface	Without exterior ambient lighting
Smartphone interface with USB port in rear	Without fire extinguisher
Software network, version 6	Without first aid kit and warning triangle
Special identification label (EU)	Without garage door opener
Standard climatic zones	Without grid connection cable for household plug, for the e-tron charging system
Standard manufacturing sequence	Without headlamp washer system, with washer fluid level indicator
Standard paint coating	Without head-up display
Standard pedals and footrest	Without heat pump
Standard seats in front	Without leather
Standard wheel bolts	Without light control
Standard-production quality	Without luggage/load compartment floor
Suspension range 04 installation control only, no requirement forecast	Without lumbar support
Swerve support and turn assist	Without memory function
Tire pressure monitoring system	Without navigation device
Tires 235/55 R19 101T/EU in front, tires 255/50 R19 103T/EU in rear	Without parking assistance/garage parking assist
Torque 310 Nm Base motor is N06/N07/N10/T3U	Without partition
Transmission for electric drive (1-speed)	Without projection light in the exterior mirrors
Trims for alloy wheels	Without rear window wiper and washer system
Twin-spoke sport leather steering wheel, flat top and bottom, with multifunction and shift paddles	Without roof insert (standard roof)
Type approval country France	Without roof rails
UWB-capable country and carrier frequency, 433.92 to 434.42 MHz	Without scuff plates
Vehicle class differentiation -89A-	Without seat heater
Vehicle inlet Combo 2 (EU)	Without side assist, exit warning and rear cross-traffic assist
Vehicle tool kit	Without special body measures
Vehicles with special upgrade measures	Without specific emission standard
	Without steering wheel heating

Without Storage package

Without trailer hitch

Without wall mount

» Tyres

MOUNTED TYRES

Make	Location	Position	Type	Rim	Dimensions	Profile depth
Pirelli	Front	Left	Summer	Aluminium	235/55 R 19 101 T	5.4 mm
Pirelli	Front	Right	Summer	Aluminium	235/55 R 19 101 T	4.8 mm
Pirelli	Rear	Left	Summer	Aluminium	235/55 R 19 101 T	4.6 mm
Pirelli	Rear	Right	Summer	Aluminium	235/55 R 19 101 T	4.3 mm

Permitted: Yes

Roadworthy: Yes

SPARE/EMERGENCY TYRE & ACCESSORIES

Repair kit present: No

Compressor present: No

No devaluation factors available

» Usage Damages

Nr	Location	Damage type	Repair type
1	Tyres	No damage	Acceptable
2	Door FR	Dent(s)	Acceptable

» Missing Parts

Nr	Location	Damage type	Repair type
1	Compressor	Missing	Replace
2	Tyre repair kit	Missing	Replace

» Commercial devaluation

Known previous damages: No
Previous damages detectable: No
Repainting present: No
Paint thickness measurement performed: Yes - no abnormalities/deviations

PAINTTHICKNESS MEASUREMENT RESULTS

The measured values were in the usual range.

At least 3 measurements were carried out per component.

» Notes On The Assessment

Details of the assignment and the scope of the assessment:

The order was placed to prepare a condition report on the described vehicle.

The vehicle condition assessment was carried out in accordance with the order on the basis of the standards for vehicle assessments specified by the client. The expert makes the findings in the individual case on the basis of his own expertise and at his own expert discretion.

Vehicle identification:

WAUZZZFZ0NP044289

VIN checked and matches documentation

Vehicle condition:

Well maintained general condition

Inspection condition:

Sufficient

Lifting platform/lifting equipment used:

No

Testdrive carried out:

No

Engine test carried out:

No

» Remarks

This copy was generated electronically. It is valid without an original signature.

» Commercial Pictures


Front Left 3/4



Front Right 3/4




Rear Left 3/4




Rear Right 3/4



Mileage



Sill outer L



Sill outer R




Chassis nr




Wheel FL



Wheel FR




Wheel RL




Wheel RR



Central console




Engine compartment



Documents




Interior arrangement




Registration Certificate



History Maintenance



Interior - front



Interior - rear





GPS/Radio


» Devaluation Damages

USAGE DAMAGES

1 - Tyres - No damage - Acceptable



2 - Door FR - Dent(s) - Acceptable



MISSING PARTS

1 - Compressor - Missing - Replace



2 - Tyre repair kit - Missing - Replace



