


» Overview

Order number: 1002059422
Order completed: 20.08.2025 10:34
Report number: 8894003
VIN: WAUZZZFZ0NP044289



Front Left 3/4



Rear Right 3/4



Mileage

» Vehicle Data

Vehicle category:	Passenger Car
Vehicle type:	SUV
Make:	Audi
Model:	Q4
Manufacturers and type code:	0588 / BZS
Date of first registration:	28.06.2022
Mileage:	66,164 km
Exterior colour:	Noir Argent-Noir/Noir-Noir/Noir/Gris Acier
Roof colour:	Blanc Glacier Métallisé
Propulsion:	Front
Fuel:	Electric
Engine size (cc):	
Performance:	150 kW (205 PS)
Length:	4,588 mm
Height:	1,632 mm
Width:	1,865 mm
Permitted total weight:	2,640 kg
Wheelbase:	2,764 mm
Number of powered axles:	2
Cylinders:	
Euronorm:	
Number of doors:	5
Number of seats:	5
Gearbox:	Automatic 1-speed
Upholstery type:	Lining fabrics
Interior colour:	Blanc Glacier Métallisé
Number of keys:	2

» Documents & Maintenance

Statutory inspection date:	
Registration certificate available:	Yes
Registration certificate received:	Yes
License plate:	None
Maintenance book:	Digital
Maintenance:	Completed
Maintenance last date:	
Maintenance last mileage:	

» Standard Equipment

12-volt outlet(s)	Drum brakes in rear
3-point seat belts in front, with pretensioner/lap belt pretensioner and height adjustment	Electric motor unit 0EH.A
Accent surfaces, Matt Black	Electric motor, system output 125 kW base motor is N06/N07/N10/T3U
Acoustic vehicle alerting system	Electric opening/closing luggage compartment lid with sensor-controlled luggage compartment release
Additional front underbody guard	Electromechanical power steering
Adhesive film	Electronic immobilizer
Assistance package	Equipment 1
Assistance package	Equipment options subset for France
Audi AG	Exterior mirror housings in body color
Audi connect emergency call & service	Exterior mirrors, electrically adjustable and heated
Audi connect remote & control for MMI basic	Exterior mirrors: aspherical on driver side, convex on front passenger side
Audi drive select	Fabric "Index"
Audi pre sense front	Floor mats, front and rear
Automatic air conditioning system	Front seats, manually adjustable
Basic	Front stabilizer bar
Basic	Functions-on-demand features not available
Battery 320 A (49 Ah)	Gear ratio 12.976
Bluetooth interface	Gloss package
Bumpers, basic	Head restraints, front
Cell module A	Headlining in cloth in specific color
Charging cable for public charging, mode 3, 22 kW (AC)	High-voltage battery 55 kWh (gross) (net: 52 kWh)
Child-proof lock, electrically operated	Inlay, Black paint finish
Clear glass	Interior lighting
Comfort auxiliary air conditioning	Interior mirror, dimming
Comfort center armrest, front	Interior with standard seats in Black fabric
Comfort center armrest, front	Internal control code
Comfort suspension	i-Size child seat mounting on the front passenger side and i-Size and top tether on the outer rear seats
Control of series production	Lane departure warning
Convenience key without Safelock	LED headlights
Country group A	LED rear lights
Coupe	Left-hand drive
Cruise control with Speedlimiter	License plate carrier in front and rear (ECE)
Daytime running light control	Loudspeakers, front (passive)
DC battery charging (type 2)	Manual in French
DC-DC converter 3.0 kW	MMI
Digital Audio Broadcasting	Model name and technology logo
Digital instrument cluster	No special edition
Disk brakes, front, 18-inch	No special purpose vehicle, standard equipment
Drive system BEV	Non-smoker's package
Driver and front passenger airbag with front passenger airbag deactivation	Not leather-covered
Driving on the right	

On-board charger up to 7.2 kW (AC)
 Operating permit, alteration
 Parking aid Plus
 Part set without country-specific prescriptive standard
 Platform group class 2
 Production wheels
 Rear and side windows with heat-insulating glazing
 Rear seat backrest, folding
 Rear stabilizer bar
 Rear-wheel drive
 Refrigerant R1234yf
 Regional code " ECE " for radio
 Safety package
 Service indicator 2 years (fix) without km, electric vehicle
 Shock absorption in front
 Side airbags, front with head airbag system and interaction airbag, front
 Single-tone horn
 Smartphone interface
 Smartphone interface with USB port in rear
 Software network, version 6
 Special identification label (EU)
 Standard climatic zones
 Standard manufacturing sequence
 Standard paint coating
 Standard pedals and footrest
 Standard seats in front
 Standard wheel bolts
 Standard-production quality
 Suspension range 04 installation control only, no requirement forecast
 Swerve assist and turn assist
 Tire pressure loss indicator
 Tires 235/55 R19 101T/EU in front, tires 255/50 R19 103T/EU in rear
 Torque 310 Nm Base motor is N06/N07/N10/T3U
 Transmission for electric drive (1-speed)
 Trims for alloy wheels
 Twin-spoke sport leather steering wheel, flat top and bottom, with multifunction and shift paddles
 Type approval country France
 UWB-capable country and carrier frequency, 433.92 to 434.42 MHz
 Vehicle class differentiation -89A-
 Vehicle inlet Combo 2 (EU)
 Vehicle tool kit

Vehicles with special upgrade measures
 Visual and acoustic seat belt reminder, electric contact in front and rear
 Weight range 7 installation control only, no requirement forecast
 Wheels, 5-arm, 8.0J x 19, 235/55/255/50 R19 tires
 Windshield with heat-reflecting glass
 With special labels safety certificates for France
 Without additional tires
 Without aluminum look in the interior
 Without antenna amplifier
 Without Audi connect navigation & infotainment
 Without Audi pre sense basic and pre sense rear
 Without camera systems/accident sensors
 Without camera-based traffic sign recognition
 Without Car2X
 Without charging cable (industrial connector)
 Without charging system
 Without Climate Control package
 Without door sill trims
 Without exterior ambient lighting
 Without fire extinguisher
 Without first aid kit and warning triangle
 Without garage door opener
 Without headlamp washer system, with washer fluid level indicator
 Without head-up display
 Without heat pump
 Without light control
 Without luggage/load compartment floor
 Without lumbar support
 Without mains cable for domestic connector for the e-tron charging system
 Without memory function
 Without navigation device
 Without parking assistance/garage parking assist
 Without partition
 Without projection light in the exterior mirrors
 Without rear window wiper and washer system
 Without roof insert (standard roof)
 Without roof rails
 Without seat heater
 Without side assist, exit warning and rear cross-traffic assist
 Without special body measures
 Without specific emission standard
 Without steering wheel heating

Without Storage package

Without trailer hitch

Without wall mount

» Tyres

MOUNTED TYRES

Make	Location	Position	Type	Rim	Dimensions	Profile depth
Pirelli	Front	Left	Summer	Aluminium	235/55 R 19 101 T	5.4 mm
Pirelli	Front	Right	Summer	Aluminium	235/55 R 19 101 T	4.8 mm
Pirelli	Rear	Left	Summer	Aluminium	235/55 R 19 101 T	4.6 mm
Pirelli	Rear	Right	Summer	Aluminium	235/55 R 19 101 T	4.3 mm

Permitted: Yes

Roadworthy: Yes

SPARE/EMERGENCY TYRE & ACCESSORIES

Repair kit present: No

Compressor present: No

No devaluation factors available

» Usage Damages

Nr	Location	Damage type	Repair type
1	Door FR	Dent(s)	Acceptable
2	Tyres	No damage	Acceptable

» Missing Parts

Nr	Location	Damage type	Repair type
1	Compressor	Missing	Replace
2	Tyre repair kit	Missing	Replace

» Commercial devaluation

Known previous damages: No
Previous damages detectable: No
Repainting present: No
Paint thickness measurement performed: Yes - no abnormalities/deviations

PAINTTHICKNESS MEASUREMENT RESULTS

The measured values were in the usual range.

At least 3 measurements were carried out per component.

» Notes On The Assessment

Details of the assignment and the scope of the assessment:

The order was placed to prepare a condition report on the described vehicle.
The vehicle condition assessment was carried out in accordance with the order on the basis of the standards for vehicle assessments specified by the client. The expert makes the findings in the individual case on the basis of his own expertise and at his own expert discretion.

Vehicle identification:

WAUZZZFZ0NP044289
VIN checked and matches documentation

Vehicle condition:

Well maintained general condition

Inspection condition:

Sufficient

Lifting platform/lifting equipment used:

No

Testdrive carried out:

No

Engine test carried out:

No

» Remarks

This copy was generated electronically. It is valid without an original signature.

» Commercial Pictures


Front Left 3/4



Front Right 3/4




Rear Left 3/4




Rear Right 3/4



Mileage



Sill outer L



Sill outer R




Chassis nr




Wheel FL



Wheel FR




Wheel RL




Wheel RR



Central console




Engine compartment



Documents




Interior arrangement




Registration Certificate



History Maintenance



Interior - front



Interior - rear



GPS/Radio




» Devaluation Damages

USAGE DAMAGES

1 - Door FR - Dent(s) - Acceptable



2 - Tyres - No damage - Acceptable



MISSING PARTS

1 - Compressor - Missing - Replace



2 - Tyre repair kit - Missing - Replace



