

# INSPECTION REPORT

End Of Contract

## GENERAL INFO

File	293891
License plate	LW9844
Vehicle identification number	WAUZZZF5NP044921
Dossier	2022076020
Make	Audi Q4 SB E-TRON 40 82kWh 5d
Mileage	69865
First registration	06/09/2022
client availability date	10/09/2025
inspectionDate	15/09/2025

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		Y	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
106	Door Rear Left // Polish	Y
139	Bumper Rear / Spoiler / Replace	Y
174	Light / Rear Right / Replace	Y
175	Light / Rear Right On Rear Bonnet / Replace	Y
191	Door Rear Right // Smart Repair Medium	Y
216	Door Front Right // Polish	Y
330	Wheel Two Tone Rear Right // Repair	N

## Damage Pictures



Wheel Two Tone Rear Right // Repair-scratch




Light / Rear Right / Replace-scratch



Light / Rear Right On Rear Bonnet / Replace-scratch



Bumper Rear / Spoiler / Replace-scratch



Door Rear Left // Polish-scratch



Door Front Right // Polish-scratch



Door Rear Right // Smart Repair Medium-dent