

# INSPECTION REPORT

End of contract

## GENERAL INFO

File	304138
License plate	GG7398
Vehicle identification number	WAUZZZGA4PA054144
Dossier	2022353040
Make	Audi Q2 30TDi 116 BED Advanced
Mileage	188705
First registration	16/06/2023
client availability date	26/01/2026
inspectionDate	28/01/2026

## CHECK POINTS

Description	Number	Present	Remark
Original license plate		N	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		N	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





## DAMAGES

Damages	Type	Acceptable
11	Bumper Front // Smart Repair Medium	N
18	Bumper Front / Spoiler / Replace	N
67	Wing Front Left / Trim / Replace	N
271	Bumper Front / Trim Left / Replace	N
233	Wing Front right // Painting	N
237	Wing Front right / Trim / Replace	N
134	Bumper Rear // Repair & Painting	N
138	Bumper Rear / Lower Cover Not Painted / Replace	N
281	Bumper Rear / Trim Left / Replace	N
283	Bumper Rear / Trim Right / Replace	N
63	Wing Front Left // Painting	Y
84	Door Front Left // Repair & Painting	N
104	Door Rear Left // Repair & Painting	N
124	Light / Rear left / Replace	Y
156	Rear Bonnet // Polish	Y
159	Rear Bonnet / Rear Window / Replace	Y
163	Roof // Repair & Painting	N
174	Light / Rear Right / Replace	Y
183	Wing Rear Right // Painting	Y
193	Door Rear Right // Painting	Y
216	Door Front Right // Polish	Y
225	Side View Mirror Right // Polish	Y
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N
431	Seat Rear Left // Repair	Y
594	Trunk Lid Interior Coating / Complete Panel / Replace	Y
624	Front Right Door Interior Coating // Replace Completely	Y
638	Rear Left Door Interior Coating / Door Handle / Replace	Y
648	Rear Right Door Interior Coating / Door Handle / Replace	Y
860	Interior Cleaning // Small	N

Damage Pictures



Damage within Renta-norm-




Light / Rear Right / Replace-scratch



Rear Bonnet / Rear Window / Replace-scratch



Wheel Alloy Rear Right // Repair-scratch



Door Front Right // Polish-scratch



Side View Mirror Right // Polish-scratch



Trunk Lid Interior Coating / Complete Panel / Replace-scratch



Rear Right Door Interior Coating / Door Handle / Replace-scratch



Front Right Door Interior Coating // Replace Completely-scratch



Seat Rear Left // Repair-scratch




Rear Left Door Interior Coating / Door Handle / Replace-scratch




Light / Rear left / Replace-scratch




Rear Bonnet // Polish-scratch



Roof // Repair & Painting-scratch + dent



Door Front Left // Repair & Painting-scratch + dent




Door Rear Left // Repair & Painting-scratch + dent






Wing Rear Right // Painting-bad repair



Door Rear Right // Painting-bad repair



Wing Front Left // Painting-bad repair





Interior Cleaning // Small-stain



Wheel Alloy Front Right // Repair-scratch



Bumper Front / Trim Left / Replace-scratch



Bumper Front / Spoiler / Replace-scratch



Bumper Front // Smart Repair Medium-scratch




Wing Front Left / Trim / Replace-scratch



Wing Front right // Painting-scratch



Wing Front right / Trim / Replace-scratch



Bumper Rear // Repair & Painting-scratch + dent



Bumper Rear / Lower Cover Not Painted / Replace-scratch



Bumper Rear / Trim Right / Replace-scratch



Bumper Rear / Trim Left / Replace-scratch