



Audi Q2: 1VTC427

Vinnnumber:	WAUZZZGA9KA043665	Versionname:	
First Registrationdate:	20/02/2019	Fiscalpower:	
Expertise Mileage:	120635	Power Kw:	
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2811
Fueltype:	Petrol		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total	2	Sun Roof electric	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Degree of wear

215/60/16/92 H				
Winter tyres:	Fr.L.	Continental: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				215/60 R 16 92 H
Tyre size FR				215/60 R 16 92 H
Tyre size RL				215/60 R 16 92 H
Tyre size RR				215/60 R 16 92 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				256
Tyre make FR				261
Tyre make RL				256
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	7460,41
Floor covering FL, Burned, Smart repair	113,74



Interior, Smell, Ozone treatment

208,23



Door panel RR, Scratch(es), Smart repair

113,74



Bumper F, Deformed / Strained, Replace and paint

1321,00



Bumper moulding F, Broken, Replace

85,26



Bumper moulding F, Broken, Replace

85,26



Headlight R, Broken, Replace

1854,38



Bumper spoiler F, Broken, Replace

87,97



Wing RL, Dent(s), Acceptable

0,00



Door RL, Dent(s) and scratch(es), Repair and paint (complete)

492,50



Door FL, Scratch(es), Repair and paint (complete)

434,50



Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)

157,71



Outside rear-view mirror base L, Scratch(es), Smart repair

113,74



Mirror side repeater L, Scratch(es), Acceptable

0,00



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)

358,51



Wing trim FL, Scratch(es), Replace

135,06



Alloy rim FL, Scratch(es), Repair and paint (complete)

129,66



Bumper R, Scratch(es), Repair and paint (complete)

289,07



Bumper moulding R, Dent(s) and scratch(es), Replace

193,30



Reflector, Broken, Replace

25,75



Door FR, Dent(s) and scratch(es), Repair and paint (complete)

434,50



Door RR, Scratch(es), Repair and paint (complete)

434,50



Wing trim RR, Scratch(es), Replace

70,73



Alloy rim RR, Scratch(es), Repair and paint (complete)

129,66



Door trim RR, Scratch(es), Replace

88,07



Door trim FR, Scratch(es), Replace

103,57

