

Vehicle details

VIN	WAUZZZGB1 MR003240	Brand	AUDI	Maintenance date	-
Licence Plate	J9-45-NV	Model	A1 Sportback 30 TFSI Pro Line S 5d	Maintenance mileage	-
Registration date	22/09/2020	Year	2020	Exterior Color	Grey Metallic
Odometer	74 479 km	Engine size	999	interior Color	Black
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	15/09/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓


Removable element

Spare wheel (wheel & tyre)	✓
Rear parcel shelf	✓

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Vredestein 215/45/17 All seasons 5.5 mm		Vredestein 215/45/17 All seasons 5.0 mm	
Pirelli 215/45/17 All seasons 5.0 mm		Pirelli 215/45/17 All seasons 5.0 mm	

Exterior

1		Part: Bumper Position: Front Damages: Scratched Severity: Length (cm) > 10 Repair mode: Repair	2		Part: Bonnet Position: - Damages: Chemical deposit Severity: - Repair mode: Lumpsum repair
5		Part: Bumper Position: Back Damages: Scratched Severity: Length (cm) > 10 Repair mode: Repair	10		Part: Alloy wheel 17" Position: Front left Damages: Scratched Severity: - Repair mode: Lumpsum repair
11		Part: Alloy wheel 17" Position: Back left Damages: Scratched Severity: - Repair mode: Lumpsum repair	12		Part: Tailgate / Boot door Position: - Damages: Chemical deposit Severity: - Repair mode: Lumpsum repair
13		Part: Roof Position: - Damages: Chemical deposit Severity: - Repair mode: Lumpsum repair			

Interior damage

3		Part: Other interior Position: - Damages: Stained/dirty Severity: - Repair mode: Cleaning gerookt in voertuig			
4		Part: Other interior Position: - Damages: Stained/dirty Severity: - Repair mode: Cleaning hond in voertuig	6		Part: Interior tailgate lining Position: Up Damages: Scratched Severity: - Repair mode: Replace
7		Part: Interior tailgate lining Position: Down Damages: Scratched Severity: - Repair mode: Replace	8		Part: Interior cleaning Position: Front Damages: Stained/dirty Severity: - Repair mode: Cleaning

9



Part

Position

Damages

Severity

Repair mode

Interior cleaning

Back

Stained/dirty

-

Cleaning