

INSPECTION REPORT


End Of Contract

GENERAL INFO

File	279824
License plate	2AQM353
Vehicle identification number	WAUZZZGBXMR064585
Dossier	2021 068 112
Make	Audi A1SB 25 TFSI 70kW Ad.Bu.E
Mileage	60421.00
First registration	11/06/2021
	19/06/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		Y	





DAMAGES

Damages	Type	Acceptable
193	Door Rear Right // Painting	N
210	Door Front Right // Smart Repair Small	N
12	Bumper Front // Smart Repair Large	N
38	Front Bonnet / Insulation / Replace	N
95	Rocker Panel Left // Polish	Y
100	Door Rear Left // Smart Repair Small	N
186	Wing Rear Right // Polish	Y
222	Side View Mirror Right // Painting	N
321	Wheel Alloy Rear Left // Repair	Y
341	Wheel Alloy Front Right // Repair	N

Damage Pictures



Wing Rear Right // Polish-scratch



Side View Mirror Right // Painting-scratch



Bumper Front // Smart Repair Large-scratch




Rocker Panel Left // Polish-scratch



Wheel Alloy Rear Left // Repair-scratch




Wheel Alloy Front Right // Repair-scratch




Door Rear Left // Smart Repair Small-scratch + dent



Front Bonnet / Insulation / Replace-tear





Door Rear Right // Painting-scratch



Door Front Right // Smart Repair Small-scratch