



Audi e-Tron: J102SF

Vinnumber:	WAUZZZGE8LB037161	Versionname:	e-Tron 55 quattro 300kW / 95kWh 4WD S Edition automaat (NEDC)
First Registrationdate:	16/10/2020	Fiscalpower:	
Expertise Mileage:	200526	Power Kw:	300
Bodytype:		Body colour:	Mythoszwart Metallic
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	4 Wheel-drive	Type of rims (mounted):	Aluminium
Fueltype:	Electric	Parking lot:	554
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	Yes		

Options

Number of keys total	1	Telephone equipment
GPS		Lining semi-leather
Autom climate control		Lining Alcantara
Windows electric F		Sun Roof electric
Radio multimedia		Panoramic roof
Keys removable towhook		Central consol F
		Luggage cover
		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors
		Tow bar removable

Degree of wear

265/15/21/108 W				
Winter tyres:	Fr.L.	Vredestein: 6,9 mm	Fr.R.	Vredestein: 4,7 mm
	Re.L.	Vredestein: 7 mm	Re.R.	Vredestein: 6,8 mm
Tyre profile depth FL				6.9
Tyre profile depth FR				4.7
Tyre profile depth RL				7.0
Tyre profile depth RR				6.8
Tyre size FL				265/15 R 21 108 W
Tyre size FR				265/15 R 21 108 W
Tyre size RL				265/15 R 21 108 W
Tyre size RR				265/15 R 21 108 W
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

Service, Maintenance, Execute



Door RL, Scratch(es), Repair and paint (complete)



Wing FL, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Replace and paint



Door FL, Scratch(es), Repair and paint (complete)



Bonnet, Scratch(es), Repair and paint (complete)



Windscreen, Crack, Replace



Bumper spoiler F, Dent(s) and scratch(es), Replace and paint



Door RR, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Replace and paint



Wheel arch cover RR, Scratch(es), Replace



Bumper moulding R, Scratch(es), Replace and paint



Bumper R, Scratch(es), Repair and paint (complete)



Ignition key, Missing, Replace

No pictures to display