

INSPECTION REPORT

End Of Contract

GENERAL INFO

File	293636
License plate	HV6116
Vehicle identification number	WAUZZZGEXNB046415
Dossier	2022 018 009
Make	Audi E-T.SB 55 95kWh 409 Qua.S
Mileage	79403
First registration	21/07/2022
client availability date	08/09/2025
inspectionDate	11/09/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	2	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		N	
Registration certificate		N	
Repair kit		Y	
RunOnFlat		N	
Charging cable		Y	
Charge back wrong tyres		N	






DAMAGES

Damages	Type	Acceptable
31	Front Bonnet // Smart Repair Small	Y
124	Light / Rear left / Replace	Y
133	Bumper Rear // Painting	Y
222	Side View Mirror Right // Painting	N
272	Bumper Front / Trim Right / Replace	N
311	Wheel Alloy Front Left // Repair	N
321	Wheel Alloy Rear Left // Repair	N
331	Wheel Alloy Rear Right // Repair	N
341	Wheel Alloy Front Right // Repair	N

Damage Pictures



Wheel Alloy Rear Right // Repair-scratch



Bumper Rear // Painting-scratch



Light / Rear left / Replace-scratch



Wheel Alloy Rear Left // Repair-scratch



Wheel Alloy Front Left // Repair-scratch



Bumper Front / Trim Right / Replace-scratch



Wheel Alloy Front Right // Repair-scratch



Front Bonnet // Smart Repair Small-dent



Side View Mirror Right // Painting-Chemical reaction